

**FORM INSP**  
Rev 05/11

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:  
11/20/2014

Document Number:  
675200813

Overall Inspection:  
SATISFACTORY

**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>334500</u>	<u>334500</u>	<u>CONKLIN, CURTIS</u>	<input type="checkbox"/>	

**Operator Information:**

OGCC Operator Number:	<u>66561</u>
Name of Operator:	<u>OXY USA INC</u>
Address:	<u>PO BOX 27757</u>
City:	<u>HOUSTON TX</u> Zip: <u>77227</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
Clark, Chris		chris_clark@oxy.com	
Kellerby, Shaun		shuan.kellerby@state.co.us	NW Supervisor

**Compliance Summary:**

QtrQtr: SWNE Sec: 23 Twp: 9S Range: 94W

**Inspector Comment:**

**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
288108	WELL	PR	05/17/2008	GW	077-09189	DAVID 23-5	PR	<input checked="" type="checkbox"/>
288109	WELL	PR	06/11/2012	GW	077-09188	DAVID 23-7	PR	<input checked="" type="checkbox"/>
288110	WELL	SI	12/11/2007	GW	077-09187	DAVID 23-10	PR	<input checked="" type="checkbox"/>
288111	WELL	PR	07/16/2009	GW	077-09186	DAVID 23-11	PR	<input checked="" type="checkbox"/>
288112	WELL	PR	03/17/2009	GW	077-09185	DAVID 23-2	PR	<input checked="" type="checkbox"/>
288113	WELL	PR	03/17/2009	GW	077-09184	DAVID 23-6	PR	<input checked="" type="checkbox"/>
288215	WELL	PR	03/17/2009	GW	077-09207	DAVID FED. 23-15	PR	<input checked="" type="checkbox"/>
288216	WELL	PR	05/30/2008	GW	077-09206	DAVID 23-12	PR	<input checked="" type="checkbox"/>
288217	WELL	PR	08/18/2009	GW	077-09205	DAVID 23-9	PR	<input checked="" type="checkbox"/>
288218	WELL	PR	01/01/2011	GW	077-09204	DAVID 23-8	PR	<input checked="" type="checkbox"/>
288219	WELL	PR	05/09/2008	GW	077-09203	DAVID 23-1	PR	<input checked="" type="checkbox"/>

293585	WELL	PR	03/17/2009	GW	077-09453	DAVID 23-7C	PR	<input checked="" type="checkbox"/>
293586	WELL	PR	01/19/2010	GW	077-09454	DAVID 23-7B	PR	<input checked="" type="checkbox"/>
293587	WELL	PR	07/16/2009	GW	077-09455	DAVID 23-7A	PR	<input checked="" type="checkbox"/>
293588	WELL	PA	10/04/2012	LO	077-09456	David 23-2B	PA	<input checked="" type="checkbox"/>
293589	WELL	PA	10/04/2012	LO	077-09457	David 23-2C	PA	<input checked="" type="checkbox"/>
293590	WELL	PA	10/04/2012	LO	077-09458	David 23-2A	PA	<input checked="" type="checkbox"/>

**Equipment:** Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location**

**Lease Road:**

Type	Satisfactory/Action Required	comment	Corrective Action	Date
Access	SATISFACTORY			

**Signs/Marker:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			
TANK LABELS/PLACARDS	SATISFACTORY			
CONTAINERS	SATISFACTORY			

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

**Spills:**

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

Multiple Spills and Releases?

**Equipment:**

Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Bird Protectors	4	SATISFACTORY			
Plunger Lift	14	SATISFACTORY			
Vertical Heated Separator	17	SATISFACTORY			

Ancillary equipment	2	SATISFACTORY	Chem units w/ containment		
---------------------	---	--------------	------------------------------	--	--

**Facilities:**  New Tank Tank ID: \_\_\_\_\_

Contents	#	Capacity	Type	SE GPS
CONDENSATE	7	300 BBLS	STEEL AST	,

S/A/V: SATISFACTORY Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Corrective Date: \_\_\_\_\_

**Paint**

Condition Adequate

Other (Content) \_\_\_\_\_

Other (Capacity) \_\_\_\_\_

Other (Type) \_\_\_\_\_

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Corrective Action \_\_\_\_\_ Corrective Date \_\_\_\_\_

Comment \_\_\_\_\_

**Venting:**

Yes/No Comment

NO

**Flaring:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

**Predrill**

Location ID: 334500

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

**S/AV:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

**S/AV:** \_\_\_\_\_ **Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Wildlife BMPs:**

**S/AV:** \_\_\_\_\_ **Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Stormwater:**

**Comment:** \_\_\_\_\_

**Staking:**

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

**Facility**

Facility ID: 288108 Type: WELL API Number: 077-09189 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Facility ID: 288109 Type: WELL API Number: 077-09188 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Facility ID: 288110 Type: WELL API Number: 077-09187 Status: SI Insp. Status: PR

**Producing Well**

Comment: PR

Facility ID: 288111	Type: WELL	API Number: 077-09186	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: PR				
Facility ID: 288112	Type: WELL	API Number: 077-09185	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: PR				
Facility ID: 288113	Type: WELL	API Number: 077-09184	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: PR				
Facility ID: 288215	Type: WELL	API Number: 077-09207	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: PR				
Facility ID: 288216	Type: WELL	API Number: 077-09206	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: PR				
Facility ID: 288217	Type: WELL	API Number: 077-09205	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: PR				
Facility ID: 288218	Type: WELL	API Number: 077-09204	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: PR				
Facility ID: 288219	Type: WELL	API Number: 077-09203	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: PR				
Facility ID: 293585	Type: WELL	API Number: 077-09453	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: PR				
Facility ID: 293586	Type: WELL	API Number: 077-09454	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: PR				
Facility ID: 293587	Type: WELL	API Number: 077-09455	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: PR				
Facility ID: 293588	Type: WELL	API Number: 077-09456	Status: PA	Insp. Status: PA

Facility ID: 293589 Type: WELL API Number: 077-09457 Status: PA Insp. Status: PA

Facility ID: 293590 Type: WELL API Number: 077-09458 Status: PA Insp. Status: PA

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_  
 Comment:   
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_  
 Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_  
 Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location:

Emission Control Burner (ECB): \_\_\_\_\_  
 Comment: \_\_\_\_\_  
 Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_  
 Comment:

1003a. Debris removed? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Waste Material Onsite? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Unused or unneeded equipment onsite? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Pit, cellars, rat holes and other bores closed? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Guy line anchors removed? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Guy line anchors marked? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_  
 Cuttings management: \_\_\_\_\_  
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_  
 Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation \_\_\_\_\_

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location  Multi-Well Location

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding	Pass					
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

S/A/V: SATISFACTOR Corrective Date: \_\_\_\_\_

Y

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT