

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



| | | | |
|----|----|----|----|
| DE | ET | OE | ES |
|----|----|----|----|

Inspection Date:
11/24/2014

Document Number:
674700625

Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

| | | | | | |
|---------------------|---------------|---------------|------------------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | 2A Doc Num: |
| | <u>334912</u> | <u>334912</u> | <u>LONGWORTH, MIKE</u> | <input type="checkbox"/> | |

Operator Information:

| | |
|-----------------------|--|
| OGCC Operator Number: | <u>96850</u> |
| Name of Operator: | <u>WPX ENERGY ROCKY MOUNTAIN LLC</u> |
| Address: | <u>1001 17TH STREET - SUITE #1200</u> |
| City: | <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u> |

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|------------------------|-------------------------------|------------------------------------|
| Kellerby, Shaun | | shaun.kellerby@state.co.us | |
| Gardner, Michael | 970/285-9377 ext. 2760 | Michael.Gardner@WPXEnergy.com | Principal Environmental Specialist |
| Moss, Brad | (970) 285-9377 | Brad.Moss@WPXEnergy.com | Production foreman |

Compliance Summary:

| QtrQtr: | <u>NENE</u> | Sec: | <u>6</u> | Twp: | <u>7S</u> | Range: | <u>95W</u> |
|------------|-------------|------------|-------------|-------------------------------|-----------|----------------|-----------------|
| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
| 06/03/2014 | 663903286 | | | SATISFACTORY | | | No |

Inspector Comment:

Related Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status | |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|-------------------------------------|
| 256254 | WELL | PR | 10/13/1999 | GW | 045-07437 | PA 41-6 | PR | <input checked="" type="checkbox"/> |
| 270605 | WELL | PR | 02/12/2005 | GW | 045-09564 | PA 341-6 | PR | <input checked="" type="checkbox"/> |
| 270606 | WELL | PR | 12/01/2004 | GW | 045-09565 | PA 441-6 | PR | <input checked="" type="checkbox"/> |
| 270607 | WELL | PR | 02/14/2005 | GW | 045-09566 | PA 344-31 | PR | <input checked="" type="checkbox"/> |
| 270627 | WELL | PR | 02/10/2005 | GW | 045-09576 | PA 541-6 | PR | <input checked="" type="checkbox"/> |

Equipment:

Location Inventory

| | | | |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

Lease Road:

| Type | Satisfactory/Action Required | comment | Corrective Action | Date |
|--------|------------------------------|---------|-------------------|------|
| Access | SATISFACTORY | | | |

Signs/Marker:

| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|----------------------|------------------------------|---------|-------------------|---------|
| CONTAINERS | SATISFACTORY | | | |
| WELLHEAD | SATISFACTORY | | | |
| TANK LABELS/PLACARDS | SATISFACTORY | | | |
| BATTERY | SATISFACTORY | | | |

Emergency Contact Number (S/A/V): SATISFACTORY Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|------------------|------------------------------|-------------------------------|----------------------|-------------------|
| UNUSED EQUIPMENT | ACTION REQUIRED | Tubing in reclaim area | Remove tubing | 12/31/2014 |

Spills:

| Type | Area | Volume | Corrective action | CA Date |
|--|------|--------|-------------------|---------|
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |

Fencing/:

| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|--------------|------------------------------|---------|-------------------|---------|
| WELLHEAD | SATISFACTORY | | | |
| SEPARATOR | SATISFACTORY | | | |
| TANK BATTERY | SATISFACTORY | | | |

Equipment:

| Type | # | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|-----------------------------|---|------------------------------|---------|-------------------|---------|
| Plunger Lift | 5 | SATISFACTORY | | | |
| Horizontal Heated Separator | 5 | SATISFACTORY | | | |
| Bird Protectors | 3 | SATISFACTORY | | | |

| | | | | |
|--------------------|--------------|-----------------------------------|---------------------|------------------|
| Facilities: | | <input type="checkbox"/> New Tank | Tank ID: _____ | |
| Contents | # | Capacity | Type | SE GPS |
| PRODUCED WATER | 1 | <100 BBLS | STEEL AST | , |
| S/A/V: | SATISFACTORY | | Comment: | |
| Corrective Action: | | | | Corrective Date: |
| <u>Paint</u> | | | | |
| Condition | Adequate | | | |
| Other (Content) | _____ | | | |
| Other (Capacity) | 80 bbl | | | |
| Other (Type) | _____ | | | |
| <u>Berms</u> | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| | | | | |
| Corrective Action | | | | Corrective Date |
| Comment | | | | |

| | | | | |
|--------------------|--------------|-----------------------------------|---------------------|------------------|
| Facilities: | | <input type="checkbox"/> New Tank | Tank ID: _____ | |
| Contents | # | Capacity | Type | SE GPS |
| CONDENSATE | 1 | 300 BBLS | STEEL AST | , |
| S/A/V: | SATISFACTORY | | Comment: | |
| Corrective Action: | | | | Corrective Date: |
| <u>Paint</u> | | | | |
| Condition | Adequate | | | |
| Other (Content) | _____ | | | |
| Other (Capacity) | _____ | | | |
| Other (Type) | _____ | | | |
| <u>Berms</u> | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| | | | | |
| Corrective Action | | | | Corrective Date |
| Comment | | | | |

| | | | | |
|--------------------|--------------|-----------------------------------|----------------|------------------|
| Facilities: | | <input type="checkbox"/> New Tank | Tank ID: _____ | |
| Contents | # | Capacity | Type | SE GPS |
| CONDENSATE | 1 | 200 BBLS | STEEL AST | , |
| S/A/V: | SATISFACTORY | | Comment: | |
| Corrective Action: | | | | Corrective Date: |
| <u>Paint</u> | | | | |
| Condition | Adequate | | | |
| Other (Content) | _____ | | | |
| Other (Capacity) | _____ | | | |
| Other (Type) | _____ | | | |
| <u>Berms</u> | | | | |

| | | | | | |
|-------------------|----------|---------------------|---------------------|-------------|-----------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Corrective Action | | | | | Corrective Date |
| Comment | | | | | |

| | |
|-----------------|---|
| Venting: | |
| Yes/No | Comment |
| YES | Venting gas off of pneumatic pump in the quad separator |

| | | | | |
|-----------------|------------------------------|---------|-------------------|---------|
| Flaring: | | | | |
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| | | | | |

Predrill

Location ID: 334912

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AV: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 256254 Type: WELL API Number: 045-07437 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Facility ID: 270605 Type: WELL API Number: 045-09564 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Facility ID: 270606 Type: WELL API Number: 045-09565 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Facility ID: 270607 Type: WELL API Number: 045-09566 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Facility ID: 270627 Type: WELL API Number: 045-09576 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
Comment: _____
Corrective Action: _____ Date: _____
Reportable: _____ GPS: Lat _____ Long _____
Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? Pass CM _____
 CA _____ CA Date _____
 Waste Material Onsite? Pass CM _____
 CA _____ CA Date _____
 Unused or unneeded equipment onsite? Fail CM Tubing in reclamation area
 CA Remove tubing CA Date 12/31/2014
 Pit, cellars, rat holes and other bores closed? Pass CM _____
 CA _____ CA Date _____
 Guy line anchors removed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors marked? Pass CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____
 Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Inspector Name: LONGWORTH, MIKE

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation

Well Release on Active Location

Multi-Well Location

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | Gravel | Pass | | | |
| Seeding | Pass | | | | | |
| | | | | MHSP | Pass | |
| | | Ditches | Fail | | | |
| | | Compaction | Pass | | | |
| Gravel | Pass | | | | | |
| Compaction | Pass | | | | | |

S/A/V: SATISFACTOR
Y _____

Corrective Date: _____

Comment: Road ditch needs cleaned and maintained.

CA: _____

Pits: NO SURFACE INDICATION OF PIT