

**FORM  
INSP**Rev  
05/11**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

DE ET OE ES

Inspection Date:  
11/25/2014Document Number:  
666800333Overall Inspection:  
SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	273707	335367	Murray, Richard	<input type="checkbox"/>	

**Operator Information:**OGCC Operator Number: 96850Name of Operator: WPX ENERGY ROCKY MOUNTAIN LLCAddress: 1001 17TH STREET - SUITE #1200City: DENVER State: CO Zip: 80202

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.us.co	
Moss, Brad		Brad.Moss@wpxenergy.com	Production Foreman
Gardner, Michael		Michael.Gardner@wpxenergy.com	Environmental Manager

**Compliance Summary:**QtrQtr: NWSE Sec: 22 Twp: 6S Range: 94W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
11/08/2013	673300118	PR	PR	SATISFACTORY	P		No
04/29/2011	200309091	PR	PR	SATISFACTORY			No
03/03/2010	200235882	PR	PR	SATISFACTORY			No
02/05/2007	200107770	PR	PR	ACTION REQUIRED	I	Fail	Yes
03/27/2006	200087819	PR	PR	SATISFACTORY	I	Pass	No
08/16/2005	200076600	PR	PR	SATISFACTORY		Pass	No

**Inspector Comment:****Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
273706	WELL	PR	04/13/2005	GW	045-10271	CLOUGH RWF 533-22	PR	<input checked="" type="checkbox"/>
273707	WELL	PR	04/02/2005	GW	045-10270	CLOUGH RWF 33-22	PR	<input checked="" type="checkbox"/>
273709	WELL	PR	04/08/2005	GW	045-10269	CLOUGH RWF 333-22	PR	<input checked="" type="checkbox"/>
273710	WELL	PR	04/13/2005	GW	045-10268	CLOUGH RWF 433-22	PR	<input checked="" type="checkbox"/>

**Equipment:****Location Inventory**

Inspector Name: Murray, Richard

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location**

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

**Spills:**

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

**Venting:**

Yes/No	Comment
YES	Bradenhead valves open

**Flaring:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

**Predrill**

Location ID: 273707

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_

Pads: \_\_\_\_\_

Soil Stockpile: \_\_\_\_\_

**S/A/V:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:****S/A/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Wildlife BMPs:****S/A/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Stormwater:****Comment:** \_\_\_\_\_**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 273706 Type: WELL API Number: 045-10271 Status: PR Insp. Status: PR

**Producing Well**

Comment: Plunger lift

Facility ID: 273707 Type: WELL API Number: 045-10270 Status: PR Insp. Status: PR

**Producing Well**

Comment: Plunger lift

Facility ID: 273709 Type: WELL API Number: 045-10269 Status: PR Insp. Status: PR

**Producing Well**

Comment: Plunger lift

Inspector Name: Murray, Richard

Facility ID: 273710 Type: WELL API Number: 045-10268 Status: PR Insp. Status: PR

**Producing Well**

Comment: Plunger lift

**Environmental**

**Spills/Releases:**

Type of Spill: Description: Estimated Spill Volume:  
Comment:  
Corrective Action: Date:  
Reportable: GPS: Lat Long  
Proximity to Surface Water: Depth to Ground Water:

**Water Well:**

Lat Long  
DWR Receipt Num: Owner Name: GPS :

**Field Parameters:**

Sample Location:

Emission Control Burner (ECB): N

Comment:

Pilot: Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: Date Interim Reclamation Completed:

Land Use:

Comment:

1003a. Debris removed? CM  
CA CA Date  
Waste Material Onsite? CM  
CA CA Date  
Unused or unneeded equipment onsite? CM  
CA CA Date  
Pit, cellars, rat holes and other bores closed? CM  
CA CA Date  
Guy line anchors removed? CM  
CA CA Date  
Guy line anchors marked? CM  
CA CA Date

1003b. Area no longer in use? Production areas stabilized ?

Inspector Name: Murray, Richard

- 1003c. Compacted areas have been cross ripped? \_\_\_\_\_
- 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_
- Cuttings management: \_\_\_\_\_
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_
- Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: SATISFACTOR \_\_\_\_\_ Corrective Date: \_\_\_\_\_

Y

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT