

**FORM INSP**  
Rev 05/11

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



|    |    |    |    |
|----|----|----|----|
| DE | ET | OE | ES |
|----|----|----|----|

Inspection Date:  
11/25/2014

Document Number:  
668500593

Overall Inspection:  
SATISFACTORY

**FIELD INSPECTION FORM**

|                     |               |               |                     |                    |                          |
|---------------------|---------------|---------------|---------------------|--------------------|--------------------------|
| Location Identifier | Facility ID   | Loc ID        | Inspector Name:     | On-Site Inspection | <input type="checkbox"/> |
|                     | <u>285624</u> | <u>324904</u> | <u>Welsh, Brian</u> | 2A Doc Num:        |                          |

**Operator Information:**

|                       |   |
|-----------------------|---|
| OGCC Operator Number: | <u>8005</u>                                       |
| Name of Operator:     | <u>BERRY ENERGY INC*WALTER</u>                    |
| Address:              | <u>1717 WASHINGTON AVE</u>                        |
| City:                 | <u>GOLDEN</u> State: <u>CO</u> Zip: <u>80401-</u> |

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

| Contact Name    | Phone          | Email                      | Comment         |
|-----------------|----------------|----------------------------|-----------------|
| Cruson, Michael | (303) 279-0190 | mcruson@berryenergyinc.com | All Inspections |

**Compliance Summary:**

QtrQtr: SWSW Sec: 9 Twp: 19S Range: 50W

| Insp. Date | Doc Num   | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|-------------------------------|----------|----------------|-----------------|
| 06/21/2011 | 200313048 | PR         | PR          | <b>ACTION REQUIRED</b>        |          |                | Yes             |
| 05/12/2010 | 200248653 | PR         | PR          | SATISFACTORY                  |          |                | No              |
| 01/04/2008 | 200125167 | PR         | PR          | <b>ACTION REQUIRED</b>        |          |                | Yes             |
| 10/25/2006 | 200098210 | DG         | WO          | SATISFACTORY                  |          | Pass           | No              |

**Inspector Comment:**

**Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |                                     |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|-------------------------------------|
| 285624      | WELL | PR     | 11/05/2006  | GW         | 061-06793 | FRAZEE B-14-2 | PR          | <input checked="" type="checkbox"/> |

**Equipment:**

Location Inventory

|                              |                        |                     |                         |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____  | Drilling Pits: _____   | Wells: _____        | Production Pits: _____  |
| Condensate Tanks: _____      | Water Tanks: _____     | Separators: _____   | Electric Motors: _____  |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____    | LACT Unit: _____    | Pump Jacks: _____       |
| Electric Generators: _____   | Gas Pipeline: _____    | Oil Pipeline: _____ | Water Pipeline: _____   |
| Gas Compressors: _____       | VOC Combustor: _____   | Oil Tanks: _____    | Dehydrator Units: _____ |
| Multi-Well Pits: _____       | Pigging Station: _____ | Flare: _____        | Fuel Tanks: _____       |

**Location**

| <b>Lease Road:</b> |                              |                           |                   |      |
|--------------------|------------------------------|---------------------------|-------------------|------|
| Type               | Satisfactory/Action Required | comment                   | Corrective Action | Date |
| Access             | SATISFACTORY                 | DIRT ROAD THROUGH PASTURE |                   |      |

| <b>Signs/Marker:</b> |                              |  |                   |         |
|----------------------|------------------------------|--|-------------------|---------|
| Type                 | Satisfactory/Action Required | Comment  | Corrective Action | CA Date |
| TANK LABELS/PLACARDS | SATISFACTORY                 | STICKERS ON WATER TANK.<br>STICKER ON SEPARATOR<br>PEELING OFF |                   |         |
| WELLHEAD             | SATISFACTORY                 | LEASE SIGN MOUNTED ON FENCE AT WELLHEAD                        |                   |         |

Emergency Contact Number (S/A/V): SATISFACTORY Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

| <b>Good Housekeeping:</b> |                              |                                |                   |         |
|---------------------------|------------------------------|--------------------------------|-------------------|---------|
| Type                      | Satisfactory/Action Required | Comment                        | Corrective Action | CA Date |
| WEEDS                     | SATISFACTORY                 | WEEDS IN FENCE AROUND WELLHEAD |                   |         |

| <b>Spills:</b>   |      |        |                   |         |
|--|------|--------|-------------------|---------|
| Type   | Area | Volume | Corrective action | CA Date |
| <input type="checkbox"/> Multiple Spills and Releases? |      |        |                   |         |

| <b>Fencing/:</b> |                              |                              |                   |         |
|------------------|------------------------------|------------------------------|-------------------|---------|
| Type             | Satisfactory/Action Required | Comment                      | Corrective Action | CA Date |
| WELLHEAD         | SATISFACTORY                 | METAL FENCE AROUND WELLHEAD  |                   |         |
| TANK BATTERY     | SATISFACTORY                 | WIRE FENCE AROUND WATER TANK |                   |         |

| <b>Equipment:</b>  |   |                              |                              |                   |         |
|--------------------|---|------------------------------|------------------------------|-------------------|---------|
| Type               | # | Satisfactory/Action Required | Comment                      | Corrective Action | CA Date |
| Deadman # & Marked | 4 | SATISFACTORY                 |                              |                   |         |
| Gas Meter Run      | 1 | SATISFACTORY                 | SOUTHEAST CORNER OF LOCATION |                   |         |
| Vertical Separator | 1 | SATISFACTORY                 | NEXT TO METER SHED           |                   |         |
| Plunger Lift       | 1 | SATISFACTORY                 |                              |                   |         |

| <b>Facilities:</b>                |   |                |      |        |  |
|-----------------------------------|---|----------------|------|--------|--|
| <input type="checkbox"/> New Tank |   | Tank ID: _____ |      |        |  |
| Contents                          | # | Capacity       | Type | SE GPS |  |
|                                   |   |                |      |        |  |

Inspector Name: Welsh, Brian

|                    |                              |                     |  |                       |  |
|--------------------|------------------------------|---------------------|--|-----------------------|--|
| PRODUCED WATER     | 1                            | 200 BBLS            | Open Top   | 38.414670,-103.022040 |  |
| S/A/V:             | SATISFACTORY                 |                     | Comment: <b>FIBERGLASS OPEN TOP WATER TANK W/ADEQUATE WILDLIFE NETTING</b> |                       |  |
| Corrective Action: |                              |                     |  | Corrective Date:      |  |
| <b>Paint</b>       |                              |                     |  |                       |  |
| Condition          | Adequate                     |                     |  |                       |  |
| Other (Content)    | _____                        |                     |  |                       |  |
| Other (Capacity)   | _____                        |                     |  |                       |  |
| Other (Type)       | _____                        |                     |  |                       |  |
| <b>Berms</b>       |                              |                     |  |                       |  |
| Type               | Capacity                     | Permeability (Wall) | Permeability (Base)  | Maintenance           |  |
| Earth              | Adequate                     | Walls Sufficient    | Base Sufficient  | Adequate              |  |
| Corrective Action  |                              |                     |  | Corrective Date       |  |
| Comment            |                              |                     |  |                       |  |
| <b>Venting:</b>    |                              |                     |  |                       |  |
| Yes/No             | Comment                      |                     |  |                       |  |
| NO                 |                              |                     |  |                       |  |
| <b>Flaring:</b>    |                              |                     |  |                       |  |
| Type               | Satisfactory/Action Required | Comment             | Corrective Action  | CA Date               |  |
|                    |                              |                     |  |                       |  |

**Predrill**

Location ID: 285624

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

**S/AV:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

**S/AV:** \_\_\_\_\_ **Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Wildlife BMPs:**

**S/AV:** \_\_\_\_\_ **Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Stormwater:**

**Comment:** \_\_\_\_\_

**Staking:**

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

**Facility**

Facility ID: 285624 Type: WELL API Number: 061-06793 Status: PR Insp. Status: PR

**Producing Well**

Comment: PRODUCING

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

1003a. Debris removed? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Waste Material Onsite? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors removed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? In Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? In

Production areas have been stabilized? Pass Segregated soils have been replaced? Pass

**RESTORATION AND REVEGETATION**

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced Pass Recontoured In 80% Revegetation In

1003 f. Weeds Noxious weeds? \_\_\_\_\_ P \_\_\_\_\_

