

**Dugan Production Co Operator #25250**  
**Tiffany #2 API# 05-067-06497**  
**Inspection #674601263**

Existing well sign on location.  
Emergency contact number posted in  
separate area across location.



Open top tank (near dehydrator)  
without signage to meet rule 210d  
requirements or adequate berming to  
meet rule 604.C.2.G requirements.



Unlabeled chemical injection  
container without spill prevention in  
place.



Open top tank (Near horizontal separator) without signage to meet rule 210d requirements and damage to wildlife screen.



Stained and saturated soils from release of fluids at drain line/ valve at bottom of horizontal separator.



Closer view of stained soils around production equipment from release at horizontal separator.





Release point of fluid from horizontal separator.



Free oil observed on compressor skid;  
Stained gravel/ soils around  
equipment. Unsatisfactory storage  
(no spill prevention BMP's) or labeling  
of fuel containers and chemical  
drums.



Free oil observed on compressor skid



Compressor exhaust being vented on ground/ stained gravel and soils.



Compressor exhaust and stained gravel/ soils.



Storage of unused equipment/ fencing on location.

