

Site Photos: API# 05-073-06299

Date: November 20, 2014



photo 1: Access Road North, to the location.



photo 2: State Dole 1-36

Site Photos: API# 05-073-06299

Date: November 20, 2014



photo 3: Center of the location facing North.



photo 4: Center of the location facing West.

Site Photos: API# 05-073-06299

Date: November 20, 2014



photo 5: Center of the location facing South.



photo 6: Center of the location facing East.

Site Photos: API# 05-073-06299

Date: November 20, 2014



photo 7: Soil stockpile located at the North side of location..



photo 8: Surface roughening around the backside (uphill side) of the soil stockpile..

Site Photos: API# 05-073-06299

Date: November 20, 2014



photo 9: Pit located at the Southeast corner of location .



photo 10: Pit located at the South side of the location.

Site Photos: API# 05-073-06299

Date: November 20, 2014



photo 9: Surface roughening around the South (downhill) side of location.



photo 10: Fence around the location was down in several sections.