

Federal 26-1

Inspection# 675200936

Debris on site.



Trash on site.



Area of partial decompaction.



Location view from NW corner.



Solar panel stand to be removed at
wellheads.

