

MERRION OIL & GAS CORP – 56680

LANIER FARMS 34-25 #1

API # 05-083-06470

Field Inspection Doc# 674601297 performed 12/09/14

Tanks requiring proper signage



Unused frac tank on well pad



Unused tubing stored on location



Oil stained soils at load out



Oil stained gravel/ soils around open top tank



Oils stained gravel/ soils around fiberglass tank



Damage to fiberglass tank and oil staining down side of tank



Bird screen requiring repair/
maintenance

