

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
12/10/2014

Document Number:
673801608

Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>318975</u>	<u>318975</u>	<u>Gomez, Jason</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number: 10311

Name of Operator: SYNERGY RESOURCES CORPORATION

Address: 20203 HIGHWAY 60

City: PLATTEVILLE State: CO Zip: 80651

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Pennington, Dave		dpennington@syrginfo.com	Synergy Inspection

Compliance Summary:

QtrQtr: SWSW Sec: 29 Twp: 1N Range: 68W

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
242625	WELL	PR	06/05/2012	OW	123-10416	PRATT 2	PR	<input checked="" type="checkbox"/>
421605	WELL	PR	02/05/2012	OW	123-32971	SRC Pratt 24-29D	PR	<input checked="" type="checkbox"/>
421628	WELL	PR	04/01/2012	OW	123-32981	SRC Pratt 13-29D	PR	<input checked="" type="checkbox"/>
421642	WELL	PR	02/05/2012	OW	123-32988	SRC Pratt 14-29D	PR	<input checked="" type="checkbox"/>
421680	WELL	AL	11/04/2011	LO	123-33010	SRC Pratt 29LD	AL	<input type="checkbox"/>
421752	WELL	AL	11/04/2011	LO	123-33042	SRC Pratt 29QD	AL	<input type="checkbox"/>
421777	WELL	AL	11/04/2011	LO	123-33056	SRC Pratt 29HD	AL	<input type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: <u>7</u>	Production Pits: _____
Condensate Tanks: _____	Water Tanks: <u>3</u>	Separators: <u>6</u>	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: <u>1</u>	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: <u>3</u>	Oil Tanks: <u>6</u>	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Signs/Marker:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			
BATTERY	SATISFACTORY			
TANK LABELS/PLACARDS	SATISFACTORY			

Emergency Contact Number (S/A/V): SATISFACTORY Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	ACTION REQUIRED	6' metal fence fencing need to be maintained	maintain fencing to comply with COGCC rules	01/10/2015
SEPARATOR	SATISFACTORY	6' metal fence		
WELLHEAD	ACTION REQUIRED	6' metal fence fencing need to be maintained	maintain fencing to comply with COGCC rules	01/10/2015
WELLHEAD	ACTION REQUIRED	6' metal fence fencing need to be maintained	maintain fencing to comply with COGCC rules	01/10/2015
WELLHEAD	ACTION REQUIRED	6' metal fence fencing need to be maintained	maintain fencing to comply with COGCC ru;es	01/10/2015
TANK BATTERY	SATISFACTORY	6' metal fence		

Equipment:					
Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Plunger Lift	4	SATISFACTORY			

Facilities: New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS

S/A/V: _____ Comment: _____

Corrective Action: _____ Corrective Date: _____

Paint

Condition	_____
-----------	-------

Other (Content) _____

Other (Capacity) _____

Inspector Name: Gomez, Jason

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Corrective Action		Corrective Date	
-------------------	--	-----------------	--

Comment	
---------	--

Venting:

Yes/No	Comment
--------	---------

NO	
----	--

Flaring:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 318975

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AV: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 242625 Type: WELL API Number: 123-10416 Status: PR Insp. Status: PR

Producing Well

Comment: **PR**

Facility ID: 421605 Type: WELL API Number: 123-32971 Status: PR Insp. Status: PR

Producing Well

Comment: **PR**

Facility ID: 421628 Type: WELL API Number: 123-32981 Status: PR Insp. Status: PR

Producing Well

Comment: **PR**

Facility ID: 421642 Type: WELL API Number: 123-32988 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Environmental

Spills/Releases:

Type of Spill: Description: Estimated Spill Volume: Comment: Corrective Action: Date: Reportable: GPS: Lat Long Proximity to Surface Water: Depth to Ground Water:

Water Well:

DWR Receipt Num: Owner Name: GPS: Lat Long

Field Parameters:

Sample Location:

Emission Control Burner (ECB): Y Comment: Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: Date Interim Reclamation Completed: Land Use: OTHER Comment: 1003a. Debris removed? Pass CM CA Date Waste Material Onsite? Pass CM CA Date Unused or unneeded equipment onsite? Pass CM CA Date Pit, cellars, rat holes and other bores closed? CM CA Date Guy line anchors removed? Pass CM CA Date Guy line anchors marked? Pass CM CA Date 1003b. Area no longer in use? Pass Production areas stabilized? Pass

Inspector Name: Gomez, Jason

1003c. Compacted areas have been cross ripped? _____
1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
Cuttings management: _____
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
Production areas have been stabilized? Pass Segregated soils have been replaced? Pass

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced Pass Recontoured Pass 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RESIDENTIAL

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Silt Fences	Fail					
Gravel	Pass					

S/A/V: SATISFACTOR Corrective Date: 01/10/2015

Y

Comment: Silt fences must be maintained

CA: Maintain or remove silt fence to comply with COGCC Rules

Pits: NO SURFACE INDICATION OF PIT