

**FORM
INSP**

Rev
05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



| | | | |
|----|----|----|----|
| DE | ET | OE | ES |
|----|----|----|----|

Inspection Date:
12/09/2014

Document Number:
668702099

Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

| | | | | | |
|---------------------|---------------|---------------|------------------------|--------------------|--------------------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | <input type="checkbox"/> |
| | <u>266670</u> | <u>321543</u> | <u>HELGELAND, GARY</u> | 2A Doc Num: | _____ |

Operator Information:

| | |
|-----------------------|---|
| OGCC Operator Number: | <u>100185</u> |
| Name of Operator: | <u>ENCANA OIL & GAS (USA) INC</u> |
| Address: | <u>370 17TH ST STE 1700</u> |
| City: | <u>DENVER</u> State: <u>CO</u> Zip: <u>80202-</u> |

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|--------------------------------|---------|
| D, J Basin | | cogcc.djinspections@encana.com | |

Compliance Summary:

| QtrQtr: | Sec: | Twp: | Range: | | | | |
|-------------|-----------|------------|-------------|-------------------------------|----------|----------------|-----------------|
| <u>NENE</u> | <u>27</u> | <u>1N</u> | <u>68W</u> | | | | |
| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
| 03/23/2011 | 200304526 | PR | PR | ACTION REQUIRED | | | Yes |
| 02/01/2005 | 200065974 | PR | PR | ACTION REQUIRED | I | Fail | Yes |
| 04/07/2004 | 200052356 | DG | WO | SATISFACTORY | F | Fail | No |
| 08/05/2003 | 200042165 | DG | ND | SATISFACTORY | | Pass | No |

Inspector Comment:

Interim reclamation inspection only.

Related Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status | |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|-------------------------------------|
| 266670 | WELL | PR | 09/11/2005 | OW | 014-20643 | STIPANOVICH 41-27 | PR | <input checked="" type="checkbox"/> |
| 417792 | WELL | PR | 03/07/2011 | OW | 014-20698 | STIPANOVICH 8-2-27 | PR | <input checked="" type="checkbox"/> |
| 417844 | WELL | PR | 03/07/2011 | OW | 014-20699 | STIPANOVICH 8-0-27 | PR | <input checked="" type="checkbox"/> |

Equipment:

Location Inventory

| | | | |
|------------------------------|-------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: <u>1</u> | Wells: <u>3</u> | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: <u>3</u> | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

Emergency Contact Number (S/AV): _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

| Spills: | | | | |
|--|------|--------|-------------------|---------|
| Type | Area | Volume | Corrective action | CA Date |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |

| Venting: | |
|-----------------|---------|
| Yes/No | Comment |
| | |

| Flaring: | | | | |
|-----------------|------------------------------|---------|-------------------|---------|
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| | | | | |

Predrill

Location ID: 266670

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AV: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 266670 Type: WELL API Number: 014-20643 Status: PR Insp. Status: PR

Facility ID: 417792 Type: WELL API Number: 014-20698 Status: PR Insp. Status: PR

Facility ID: 417844 Type: WELL API Number: 014-20699 Status: PR Insp. Status: PR

Producing Well

Comment: Interim reclamation inspection only.

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
 Comment: _____
 Corrective Action: _____ Date: _____
 Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well: _____ Lat _____ Long _____
 DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters: _____

Sample Location: _____

Emission Control Burner (ECB): _____
 Comment: _____
 Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: IMPROVED PASTURE

Comment: _____

- 1003a. Debris removed? Pass CM _____
 CA _____ CA Date _____
- Waste Material Onsite? Pass CM _____
 CA _____ CA Date _____
- Unused or unneeded equipment onsite? Pass CM _____
 CA _____ CA Date _____
- Pit, cellars, rat holes and other bores closed? Pass CM _____
 CA _____ CA Date _____
- Guy line anchors removed? Pass CM _____
 CA _____ CA Date _____
- Guy line anchors marked? _____ CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? Pass

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Pass

Production areas have been stabilized? Pass Segregated soils have been replaced? Pass

RESTORATION AND REVEGETATION

Cropland

Inspector Name: HELGELAND, GARY

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced Pass Recontoured Pass 80% Revegetation Pass

1003 f. Weeds Noxious weeds? _____ P _____

Comment: _____

Overall Interim Reclamation Pass

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: IMPROVED PASTURE

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | | | |

S/A/V: SATISFACTOR Corrective Date: _____

Y

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------------|---|
| 668702099 | INSPECTION APPROVED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3504251 |
| 668702100 | Wells | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3504240 |