

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

DE ET OE ES

Inspection Date:
12/12/2014Document Number:
666800418Overall Inspection:
SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	295307	334714	Murray, Richard	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 10433Name of Operator: PICEANCE ENERGY LLCAddress: 1512 LARIMER STREET #1000City: DENVER State: CO Zip: 80202

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Bankert, Wayne		wbankert@laramie-energy.com	Senior Regulatory & Environmental Coordinator
Kellerby, Shaun		Shaun.Kellerby@state.co.us	NW Field Supervisor

Compliance Summary:QtrQtr: SENW Sec: 31 Twp: 6S Range: 93W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
06/14/2012	663800388	PR	PR	SATISFACTORY			No
12/21/2011	663800017	PR	PR	SATISFACTORY			No

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
295307	WELL	PR	04/03/2008	GW	045-15725	LEVERICH FEDERAL 31-06D	PR	<input checked="" type="checkbox"/>
295308	WELL	PR	12/13/2008	GW	045-15726	LEVERICH 31-05B	PR	<input checked="" type="checkbox"/>
295309	WELL	PR	10/06/2008	GW	045-15727	LEVERICH 31-04B	PR	<input checked="" type="checkbox"/>
295310	WELL	PR	09/28/2008	GW	045-15728	LEVERICH FEDERAL 31-03D	PR	<input checked="" type="checkbox"/>

Equipment:**Location Inventory**

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Inspector Name: Murray, Richard

Location

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Equipment:

Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Gas Meter Run	4	SATISFACTORY			
Vertical Heated Separator	4	SATISFACTORY			
Horizontal Heated Separator	0	SATISFACTORY			
Ancillary equipment	1	SATISFACTORY	Chemical unit at wellhead		
Emission Control Device	1	SATISFACTORY			

Facilities:

☐ New Tank

Tank ID: _____

Contents	#	Capacity	Type	SE GPS
				,

S/A/V: _____ Comment: _____

Corrective Action: _____ Corrective Date: _____

Paint

Condition _____

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Corrective Action _____ Corrective Date _____

Comment _____

Facilities:

☐ New Tank

Tank ID: _____

Contents	#	Capacity	Type	SE GPS
CONDENSATE	2	400 BBLS	STEEL AST	39.482990,-107.820570

S/A/V: SATISFACTORY Comment: _____

Corrective Action: _____ Corrective Date: _____

Paint

Condition Adequate

Other (Content) _____

Inspector Name: Murray, Richard

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Corrective Action		Corrective Date	
Comment			

Venting:		
Yes/No	Comment	
NO		

Flaring:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 295307

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 295307 Type: WELL API Number: 045-15725 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Facility ID: 295308 Type: WELL API Number: 045-15726 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Facility ID: 295309 Type: WELL API Number: 045-15727 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Inspector Name: Murray, Richard

Facility ID: 295310 Type: WELL API Number: 045-15728 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Environmental

Spills/Releases:

Type of Spill: Description: Estimated Spill Volume:
Comment:
Corrective Action: Date:
Reportable: GPS: Lat Long
Proximity to Surface Water: Depth to Ground Water:

Water Well:

Lat Long
DWR Receipt Num: Owner Name: GPS :

Field Parameters:

Sample Location:

Emission Control Burner (ECB): Y

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: Date Interim Reclamation Completed:

Land Use:

Comment:

1003a. Debris removed? Pass CM CA Date
Waste Material Onsite? Pass CM CA Date
Unused or unneeded equipment onsite? Pass CM CA Date
Pit, cellars, rat holes and other bores closed? Pass CM CA Date
Guy line anchors removed? CM CA Date
Guy line anchors marked? Pass CM CA Date

1003b. Area no longer in use? In Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____ In _____

1003d. Drilling pit closed? _____ Pass _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment:

Overall Interim Reclamation

Date Final Reclamation Started: _____	Date Final Reclamation Completed: _____
Final Land Use: _____	
Reminder: _____	
Comment: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>	
Well plugged _____	Pit mouse/rat holes, cellars backfilled _____
Debris removed _____	No disturbance /Location never built _____
Access Roads _____	Regraded _____
	Contoured _____
	Culverts removed _____
Gravel removed _____	
Location and associated production facilities reclaimed _____	Locations, facilities, roads, recontoured _____
Compaction alleviation _____	Dust and erosion control _____
Non cropland: Revegetated 80% _____	Cropland: perennial forage _____
Weeds present _____	Subsidence _____
Comment: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>	
Corrective Action: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>	Date _____
Overall Final Reclamation _____	Well Release on Active Location <input type="checkbox"/> Multi-Well Location <input type="checkbox"/>

<u>Storm Water:</u>						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
Retention Ponds	Pass					
Ditches	Pass					
		Sediment Traps	Pass			
		Ditches	Pass			
Sediment Traps	Pass					
Drains	Pass					
Rip Rap	Pass					

Inspector Name: Murray, Richard

		Culverts	Pass			
S/A/V: SATISFACTOR Corrective Date: _____						
Y _____						
Comment: _____						
CA: _____						
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						