

Currier 14-16

Inspection# 675200944

Weeds and vegetation in
containment.



Vegetation around wellhead.



Separator that is not sitting
vertical.



Example of debris around location.

