

Site Photos: API# 05-071-09033

Date: December 17, 2014



photo 1: Access road north to the location off of the main road.



photo 2: Gravel and culverts have not been removed and the road has not been reclaimed.

Site Photos: API# 05-071-09033

Date: December 17, 2014



photo 3: Gravel and culverts have not been removed and the road has not been reclaimed.



photo 4: Gravel remains along the access road and the road has not been recontoured.

Site Photos: API# 05-071-09033

Date: December 17, 2014



photo 5: Erosion is occurring off of the access road along the access road.



photo 6: Facing north from the access road towards the location.

Site Photos: API# 05-071-09033

Date: December 17, 2014



photo 7: South side of the location facing north.



photo 8: Center of the location facing northeast.

Site Photos: API# 05-071-09033

Date: December 17, 2014



photo 6: Northwest corner of the location facing southeast.



photo 6: Northeast corner of the location facing south.