

Comments:

ENGINEERING AND ENVIRONMENTAL WORK

NOTICE OF CONTINUED TEMPORARILY ABANDONED STATUS

Indicate why the well is temporarily abandoned and describe future plans for utilization in the COMMENTS box below or provide as an attachment, as required by Rule 319.b.(3).

Date well temporarily abandoned 03/11/2009 Has Production Equipment been removed from site? Yes

Mechanical Integrity Test (MIT) required if shut in longer than 2 years. Date of last MIT 05/12/2013

SPUD DATE: _____

TECHNICAL ENGINEERING AND ENVIRONMENTAL WORK

Details of work must be described in full in the COMMENTS below or provided as an attachment.

NOTICE OF INTENT Approximate Start Date _____

REPORT OF WORK DONE Date Work Completed _____

<input type="checkbox"/> Intent to Recomplete (Form 2 also required)	<input type="checkbox"/> Request to Vent or Flare	<input type="checkbox"/> E&P Waste Mangement Plan
<input type="checkbox"/> Change Drilling Plan	<input type="checkbox"/> Repair Well	<input type="checkbox"/> Beneficial Reuse of E&P Waste
<input type="checkbox"/> Gross Interval Change	<input type="checkbox"/> Rule 502 variance requested. Must provide detailed info regarding request.	
<input type="checkbox"/> Other _____	<input type="checkbox"/> Status Update/Change of Remediation Plans for Spills and Releases	

COMMENTS:

resolving well status issues with Bob Koehler, COGCC. TA status previously reported via sundry. Since this was not the appropriate wayto submit TA status, KM submitted form 5A to declare so.

1. Date well TA'd: 3/11/2009- date bridge plug set
2. Production equipment was removed
3. Date of last MIT: 5/12/2013
4. How well is closed to atmosphere: BRIDGE PLUG
5. producing too much water; waiting on results of HD3, drilling 12/2014

CASING AND CEMENTING CHANGES

Casing Type	Size	Of	/	Hole	Size	Of	/	Casing	Wt/Ft	Csg/LinTop	Setting Depth	Sacks of Cement	Cement Bottom	Cement Top

H2S REPORTING

Data Fields in this section are intended to document Sample and Location Data associated with the collection of a Gas Sample that is submitted for Laboratory Analysis.

Gas Analysis Report must be attached.

H2S Concentration: _____ in ppm (parts per million) Date of Measurement or Sample Collection _____

Description of Sample Point:

Absolute Open Flow Potential _____ in CFPD (cubic feet per day)

Description of Release Potential and Duration (If flow is not open to the atmosphere, identify the duration in which the container or pipeline would likely be opened for servicing operations.):

--

Distance to nearest occupied residence, school, church, park, school bus stop, place of business, or other areas where the public could reasonably be expected to frequent: _____

Distance to nearest Federal, State, County, or municipal road or highway owned and principally maintained for public use: _____

COMMENTS:

--

Best Management Practices

No BMP/COA Type

Description

No BMP/COA Type	Description

Operator Comments:

Sundry - continued TA status; next update due in one year 12/16/2015. Attached WBD is the most current one and should be the one on file with COGCC

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Paul E. Belanger
Title: Regulatory Contractor Email: Paul_Belanger@kindermorgan.com Date: 12/16/2014

Based on the information provided herein, this Sundry Notice (Form 4) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: Bradshaw, Leigh Date: 12/23/2014

CONDITIONS OF APPROVAL, IF ANY:

COA Type

Description

COA Type	Description

General Comments

User Group

Comment

Comment Date

User Group	Comment	Comment Date

Total: 0 comment(s)

Attachment Check List

Att Doc Num

Name

400752614	FORM 4 SUBMITTED
400752615	WELLBORE DIAGRAM

Total Attach: 2 Files