

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES
----	----	----	----

Inspection Date:

12/23/2014

Document Number:

673801650

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	321308	321308	Gomez, Jason	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1625 BROADWAY STE 2200City: DENVER State: CO Zip: 80202

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Fogel, Heather		HFogel@nobleenergyinc.com	

Compliance Summary:QtrQtr: SENW Sec: 1 Twp: 1S Range: 69W**Inspector Comment:****Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
206633	WELL	PR	12/20/1992	GW	013-06128	WANEKA 1-1	PR	<input checked="" type="checkbox"/>
435833	TANK BATTERY	AC	04/14/2009	-	-	WANEKA-61S69W 1SENW	AC	<input checked="" type="checkbox"/>
435834	TANK BATTERY	AC	04/14/2009	-	-	WANEKA-61S69W 1SENW	AC	<input checked="" type="checkbox"/>

Equipment:**Location Inventory**

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location**Signs/Marker:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
TANK LABELS/PLACARDS	SATISFACTORY			
WELLHEAD	SATISFACTORY			

Inspector Name: Gomez, Jason

BATTERY	SATISFACTORY			
---------	--------------	--	--	--

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?**Fencing/:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
SEPARATOR	SATISFACTORY	Fabricated Metal		
OTHER	SATISFACTORY	Fabricated Metal around compressor		
TANK BATTERY	SATISFACTORY	Wire		

Equipment:

Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Bird Protectors	2	SATISFACTORY			
Compressor	1	SATISFACTORY			
Plunger Lift	1	SATISFACTORY			
Vertical Separator	1	SATISFACTORY			
Horizontal Heated Separator	1	SATISFACTORY			
Emission Control Device	1	SATISFACTORY			
Gas Meter Run	3	SATISFACTORY			
Pig Station	1	SATISFACTORY			

Facilities:☐ New Tank

Tank ID: _____

Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	1	<50 BBLS	CONCRETE SUMP/VAULT	,

S/A/V: SATISFACTORY	Comment:
---------------------	----------

Corrective Action:	Corrective Date:
--------------------	------------------

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Corrective Action	Corrective Date
-------------------	-----------------

Comment

Facilities:		New Tank		Tank ID: _____	
Contents	#	Capacity	Type	SE GPS	
USED OIL	1	<50 BBLS	CONCRETE SUMP/VAULT		
S/A/V:	SATISFACTORY		Comment:		
Corrective Action:				Corrective Date:	

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Corrective Action				Corrective Date
Comment				

Facilities:	<input type="checkbox"/> New Tank	Tank ID: _____
--------------------	-----------------------------------	----------------

Contents	#	Capacity	Type	SE GPS
LUBE OIL	1	<50 BBLS	STEEL AST	
S/A/V:	SATISFACTORY		Comment:	
Corrective Action:				Corrective Date:

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Corrective Action				Corrective Date
Comment				

Facilities:	<input type="checkbox"/> New Tank	Tank ID: _____
--------------------	-----------------------------------	----------------

Contents	#	Capacity	Type	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST	
S/A/V:	SATISFACTORY		Comment:	
Corrective Action:				Corrective Date:

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Inspector Name: Gomez, Jason

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Corrective Action					Corrective Date
Comment					

Venting:	
Yes/No	Comment
NO	

Flaring:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 321308

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/A/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/A/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 206633 Type: WELL API Number: 013-06128 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Facility ID: 435833 Type: TANK API Number: - Status: AC Insp. Status: AC

Facility ID: 435834 Type: TANK API Number: - Status: AC Insp. Status: AC

Environmental**Spills/Releases:**

Type of Spill: Description: Estimated Spill Volume:

Comment:

Corrective Action: Date:

Reportable: GPS: Lat Long

Proximity to Surface Water: Depth to Ground Water:

Water Well:

DWR Receipt Num: Owner Name: GPS : Lat Long

Field Parameters:

Sample Location:

Emission Control Burner (ECB): Y

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: Date Interim Reclamation Completed:

Land Use:

Comment:

1003a. Debris removed? Pass CM

CA CA Date

Waste Material Onsite? Pass CM

CA CA Date

Unused or unneeded equipment onsite? Pass CM

CA CA Date

Pit, cellars, rat holes and other bores closed? CM

CA CA Date

Guy line anchors removed? Pass CM

CA CA Date

Inspector Name: Gomez, Jason

Guy line anchors marked? CM
CA CA Date

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped?

1003d. Drilling pit closed? Subsidence over on drill pit?

Cuttings management:

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing?

Production areas have been stabilized? Pass Segregated soils have been replaced? Pass

RESTORATION AND REVEGETATION

Cropland

Top soil replaced Pass Recontoured Pass Perennial forage re-established

Non-Cropland

Top soil replaced Recontoured 80% Revegetation

1003 f. Weeds Noxious weeds?

Comment:

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: Date Final Reclamation Completed:

Final Land Use:

Reminder:

Comment:

Well plugged Pit mouse/rat holes, cellars backfilled

Debris removed No disturbance /Location never built

Access Roads Regraded Contoured Culverts removed

Gravel removed

Location and associated production facilities reclaimed Locations, facilities, roads, recontoured

Compaction alleviation Dust and erosion control

Non cropland: Revegetated 80% Cropland: perennial forage

Weeds present Subsidence

Comment:

Corrective Action: Date

Overall Final Reclamation Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

S/A/V: SATISFACTOR Corrective Date:

Y

Comment:

CA:

Pits: ☒ NO SURFACE INDICATION OF PIT