

FORM INSP
Rev 05/11

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
01/02/2015

Document Number:
666800465

Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>293394</u>	<u>334693</u>	<u>Murray, Richard</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>100185</u>
Name of Operator:	<u>ENCANA OIL & GAS (USA) INC</u>
Address:	<u>370 17TH ST STE 1700</u>
City:	<u>DENVER</u> State: <u>CO</u> Zip: <u>80202-</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

Compliance Summary:

QtrQtr: SENW Sec: 24 Twp: 7S Range: 93W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
05/28/2013	670200500	PR	SI	SATISFACTORY			No
01/30/2009	200203418	PR	PR	ACTION REQUIRED			Yes

Inspector Comment:

Action required items noted on inspection document number 670200500 dated 5/28/2013 have been met

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
285600	WELL	PR	06/14/2010	GW	045-12525	COUEY 24-6 (F24W)	PR	<input checked="" type="checkbox"/>
285601	WELL	PR	07/12/2007	GW	045-12524	COUEY FEDERAL 24-3 (F24W)	PR	<input checked="" type="checkbox"/>
285602	WELL	PR	07/15/2007	GW	045-12523	COUEY FEDERAL 24-3D (F24W)	PR	<input checked="" type="checkbox"/>
293065	WELL	PR	02/01/2011	GW	045-14862	COUEY 24-7 (F24W)	PR	<input checked="" type="checkbox"/>
293066	WELL	PR	01/01/2011	GW	045-14863	COUEY 24-10B (F24W)	PR	<input checked="" type="checkbox"/>
293067	WELL	PR	09/21/2008	GW	045-14864	COUEY 24-10 (F24W)	PR	<input checked="" type="checkbox"/>
293068	WELL	PR	02/01/2011	GW	045-14865	COUEY 24-11 (F24W)	PR	<input checked="" type="checkbox"/>
293159	WELL	PR	02/01/2011	GW	045-14907	COUEY 24-2D (F24W)	PR	<input checked="" type="checkbox"/>
293394	WELL	PR	05/01/2014	GW	045-14954	COUEY 24-6D (F24W)	SI	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

Inspector Name: Murray, Richard

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
BATTERY	SATISFACTORY			

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

Multiple Spills and Releases?

Venting:

Yes/No	Comment
NO	

Flaring:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 293394

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AV: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 285600 Type: WELL API Number: 045-12525 Status: PR Insp. Status: PR

Producing Well

Comment: **Plunger lift**

Facility ID: 285601 Type: WELL API Number: 045-12524 Status: PR Insp. Status: PR

Producing Well

Comment: **Plunger lift**

Facility ID: 285602 Type: WELL API Number: 045-12523 Status: PR Insp. Status: PR

Producing Well

Comment: **Plunger lift**

Facility ID: 293065 Type: WELL API Number: 045-14862 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Facility ID: 293066 Type: WELL API Number: 045-14863 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Facility ID: 293067 Type: WELL API Number: 045-14864 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Facility ID: 293068 Type: WELL API Number: 045-14865 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Facility ID: 293159 Type: WELL API Number: 045-14907 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Facility ID: 293394 Type: WELL API Number: 045-14954 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

S/A/V: _____ CA Date: _____

CA: _____

Comment: Last production numers posted May 2014

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS: _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): Y

Comment: _____

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

- 1003a. Debris removed? Pass CM _____
CA _____ CA Date _____
- Waste Material Onsite? Pass CM _____
CA _____ CA Date _____
- Unused or unneeded equipment onsite? Pass CM _____
CA _____ CA Date _____
- Pit, cellars, rat holes and other bores closed? Pass CM _____
CA _____ CA Date _____
- Guy line anchors removed? _____ CM _____
CA _____ CA Date _____
- Guy line anchors marked? Pass CM _____
CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? Pass

1003d. Drilling pit closed? Pass Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Inspector Name: Murray, Richard

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location

Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Waddles	Pass			
Slope Roughening	Pass					
Ditches	Pass					
		Ditches	Pass			
		Culverts	Pass			
Berms	Pass					
Drains	Pass					

S/A/V: SATISFACTOR
Y

Corrective Date: _____

Comment: Sow covered location

CA: _____

Pits: NO SURFACE INDICATION OF PIT