

**Dugan Production Co Operator #25250**  
**Tiffany #2 API# 05-067-06497**  
**Follow up Inspection #674601359**

Existing well sign/ emergency contact number



New berming; New tank sign; New wildlife screening over open top tank



Unused equipment/ chemical injection system removed from wellhead area.



Containment installed at exhaust  
outlet; New gravel around equipment



New labeling on containers/ lube oil  
drums; contents shown on front side



Compressor skid; self inspection/ spill  
prevention practices in place





Horizontal heated separator drain  
plumbed to tank; Gravel added  
around equipment.



Berm maintenance completed; New  
signage installed; new wildlife screen



Housekeeping completed; Gravel  
base added around equipment

