

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

| DE | ET | OE | ES |
|----|----|----|----|
|----|----|----|----|

Inspection Date:
01/14/2015Document Number:
668500817Overall Inspection:
SATISFACTORY**FIELD INSPECTION FORM**

| | | | | | |
|---------------------|-------------|--------|-----------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | 2A Doc Num: |
| | 254237 | 304231 | Welsh, Brian | <input type="checkbox"/> | |

Operator Information:OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 16000 DALLAS PARKWAY #875City: DALLAS State: TX Zip: 75248-

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|---------------------|----------------------|---------------------------------|---------|
| Eisterhold, Rachael | 918-585-1650 ext 212 | regulatory@foundationenergy.com | |

Compliance Summary:QtrQtr: NENW Sec: 7 Twp: 4S Range: 43W

| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|-------------------------------|----------|----------------|-----------------|
| 09/18/2013 | 668601442 | PR | PR | SATISFACTORY | P | | No |
| 06/01/2011 | 200312635 | PR | PR | SATISFACTORY | | | No |
| 05/21/2009 | 200211003 | PR | PR | SATISFACTORY | | | No |
| 08/13/1999 | 873553 | PR | PR | SATISFACTORY | | Pass | No |

Inspector Comment:**Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status | |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|-------------------------------------|
| 254237 | WELL | PR | 07/15/1998 | GW | 125-08115 | HELLING 21-7 | PR | <input checked="" type="checkbox"/> |

Equipment:Location Inventory

| | | | |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

| Lease Road: | | | | |
|--------------------|------------------------------|--|-------------------|------|
| Type | Satisfactory/Action Required | comment | Corrective Action | Date |
| Access | SATISFACTORY | PARTIALLY GRAVELED TRAIL THROUGH FARM GROUND | | |

| Signs/Marker: | | | | |
|----------------------|------------------------------|----------------------------------|-------------------|---------|
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| WELLHEAD | SATISFACTORY | LEASE SIGN MOUNTED TO METER SHED | | |
| TANK LABELS/PLACARDS | SATISFACTORY | METAL SIGN BY WATER TANK | | |

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

| Spills: | | | | |
|--|------|--------|-------------------|---------|
| Type | Area | Volume | Corrective action | CA Date |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |

| Fencing/: | | | | |
|------------------|------------------------------|---|-------------------|---------|
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| LOCATION | SATISFACTORY | PIPE FENCE AROUND UNIT, WELLHEAD, METER SHED AND WATER TANK | | |

| Equipment: | | | | | |
|---------------------|---|------------------------------|---|-------------------|---------|
| Type | # | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| Vertical Separator | 1 | SATISFACTORY | VERTICAL GAS SEPARATOR IN METER SHED | | |
| Prime Mover | 0 | SATISFACTORY | REMOVED FROM UNIT | | |
| Pump Jack | 1 | SATISFACTORY | JENSEN UNIT | | |
| Ancillary equipment | 2 | SATISFACTORY | ELECTRIC PANEL AND GAS SCRUBBER IN STEEL BOX FOR DOMESTIC USE | | |
| Gas Meter Run | 1 | SATISFACTORY | | | |

| Facilities: | | | | |
|-----------------------------------|---|----------------|----------------|------------------------|
| <input type="checkbox"/> New Tank | | Tank ID: _____ | | |
| Contents | # | Capacity | Type | SE GPS |
| PRODUCED WATER | 1 | OTHER | PBV FIBERGLASS | 39.729830,-102.228980 |
| S/A/V: SATISFACTORY | Comment: FIBERGLASS WATER TANK 50% BURIED | | | |
| Corrective Action: | | | | Corrective Date: _____ |

Inspector Name: Welsh, Brian

Paint

Condition

Other (Content)

Other (Capacity) 210BBL

Other (Type)

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|------|----------|---------------------|---------------------|-------------|
| | | | | |

Corrective Action

Corrective Date

Comment

Venting:

Yes/No

Comment

NO

Flaring:

Type

Satisfactory/Action Required

Comment

Corrective Action

CA Date

Predrill

Location ID: 254237

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 254237 Type: WELL API Number: 125-08115 Status: PR Insp. Status: PR

Producing Well

Comment: PRODUCING. CASING PRODUCTION

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Inspector Name: Welsh, Brian

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? Pass CM _____
CA _____ CA Date _____
Waste Material Onsite? Pass CM _____
CA _____ CA Date _____
Unused or unneeded equipment onsite? Pass CM _____
CA _____ CA Date _____
Pit, cellars, rat holes and other bores closed? Pass CM _____
CA _____ CA Date _____
Guy line anchors removed? _____ CM _____
CA _____ CA Date _____
Guy line anchors marked? _____ CM _____
CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Inspector Name: Welsh, Brian

Comment:

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started:

Date Final Reclamation Completed:

Final Land Use:

Reminder:

Comment:

Well plugged

Pit mouse/rat holes, cellars backfilled

Debris removed

No disturbance /Location never built

Access Roads Regraded

Contoured

Culverts removed

Gravel removed

Location and associated production facilities reclaimed

Locations, facilities, roads, recontoured

Compaction alleviation

Dust and erosion control

Non cropland: Revegetated 80%

Cropland: perennial forage

Weeds present

Subsidence

Comment:

Corrective Action:

Date

Overall Final Reclamation

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Other | Pass | Compaction | Pass | | | |
| | | Gravel | Pass | | | |

S/A/V: SATISFACTOR
Y

Corrective Date:

Comment: **ACCESS AND LOCATION ARE FARMED OVER**

CA:

Pits: ☒ NO SURFACE INDICATION OF PIT