

G 18 OU Pad

Inspection# 675201057

Rutting and erosion in roadway.
Photo 1



Rutting and erosion in roadway.
Photo 2



Rutting on location.

