



October 2, 2014

Jim Hughes
Environmental Protection Specialist
Colorado Oil and Gas Conservation Commission

**RE: Remedial Excavation Supplemental Report
CB #3, API Number: 05-083-06715
L7, Section 11, T38N, R19W, Montezuma County, Colorado**

Dear Mr. Hughes:

On September 23, 2014, Kinder Morgan completed an initial release mitigation and remedial excavation at the Kinder Morgan CB-3 well site, located in Montezuma County, Colorado. The release occurred September 22, 2014, and consisted of approximately 43 barrels (bbls) drilling fluid. An estimated 37 bbls were immediately recovered using an on-site vacuum truck, and 6 bbls were unrecoverable. This letter is the supplemental report for the initial release mitigation. Clarifications on the cause of the spill and disposal manifests for the soil removed from the well pad are included with this report.

In the initial report, Form 19, reference to an H₂S kick was reported to be the cause of the spill. Clarification of this reference is as follows:


The referenced kick was H₂S gas pressure in the fluid stream and the well was fully under control the whole time. The alarms were triggered and the crews evacuated the rig floor to a predetermined muster area. The pumps were running during the evacuation, which caused the shaker to get overloaded to a point fluid overran the screens and exited the area of the shaker that normally drops out only drill cuttings. That exit point caused fluids to overtop the cuttings bin and spill to the containment area. This was remedied quickly the area was determined to be safe to re-enter.

Recommendations

Kinder Morgan will complete the remedial excavation at CB-3 when the drill rig and associated equipment is removed. Kinder Morgan will submit a final remediation report upon receipt of confirmation laboratory analysis.

If you have any questions about this report or site conditions, please do not hesitate to contact Tami Knight at (970) 882-5520.

Sincerely,



Tami C. Knight, CHMM
Operations Project Manager

Attachments:

Disposal Manifests



Industrial Ecosystems Inc.
Soil Reclamation Center

P.O. Box 2043
Farmington NM 87499

Phone: (505) 632-1782
Fax: (505) 632-1876

#49 CR 3150
Aztec NM 87410

Material Entry Record

Date: 9-22-14 Company Representatives Name: Neil Jones
Generator of Material: KINDER Morgan Phone Number: 970-560-9397
Origin of Material (Location): CB # Drill Location (Rig M#13) Rig # M#13
Material Transported by: Lingo Trucking H2S Gas ☐ Non-Detect ☐ Detect: Level ____
Driver's Name: Cody Lingo ____ Chlorides ____ PH ____ TDS
Driver's Cell #: ____
Truck Number: 4 Paint Filter Test: ☐ Passed ☐ Failed
Pile Number: ____ ☐ Pit ☐ Tanks
☐ Logged in Corresponding BioPile Sheet

☐ DENIED / REJECTED


Type of Material

Soil ☒
Gravel ☒
Solidified Liquid ☒
Other ☐



Tank Bottom Sludge ☐
Tank Cleaning Residue ☐
Charcoal Filter Media ☐

Washout by: ____



Dilution Material ____

Amount of Material ____

	Load #1	Load #2	Load #3	Load #4	Load #5	Load #6	Load #7	Load #8	Load #9	Load #10
Cubic Yards	18	18	18							
Barrels	0	0	0							
Washout	0	0	0							
Truck #	4	04								
Time In	8:11pm	9:40pm	11:35pm							
Time Out	8:45pm	10:07pm	11:50pm							
Login Initials	MS	MS	MS							

Exempt ☐

XXX

Non Exempt ☐

I certify that the quantity and type of waste is that listed above. To the best of my knowledge, no other quantities or types of wastes have been added or removed.

Driver's signature: Cody Lingo

Attendant's Signature: Michael Story

*Attach copy of test results to C-138

54cy