



Photo 1. Deep ruts and ponding at the entrance to the well pad.





Photo 2. View of dense kochia (*Kochia scoparia*) patch approximately 125 feet by 75 feet long, in northeastern corner of project area. Tire tracks appear to be caused by vehicles avoiding muddy pool at well pad entrance.





Photo 3. View of dense kochia (*Kochia scoparia*) patch approximately 150 feet by 150 feet long, in southern portion of project area.





Photo 4. Little vegetation established on southern fill slope.





Photo 5. Birdseye view of Scotch thistle (*Onopordum acanthium*) rosettes within interim reclamation area.





Photo 6. View from northwestern corner of project area facing center. Vegetation appears to be progressing in the western portion of the project area.



Photo 7. View from southwestern corner of project area facing center.