



Photo 1. View of northern portion of project area from northwestern corner of facing eastward. Dried Russian knapweed plants can be seen mixed throughout grassy vegetation.





Photo 2. View of vegetation progressing in southwestern portion of project area from western edge facing southeastward.





Photo 3. View of dried Scotch thistle plant within project area.





Photo 4. View of large Russian thistle plants in the working area of the well pad.





Photo 5. View of erosional downcutting on northern edge of working area and access road.