

Inspector Name: Gomez, Jason

**FORM  
INSP**Rev  
05/11**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES
----	----	----	----

Inspection Date:

01/14/2015

Document Number:

673801675

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection <input type="checkbox"/>
	330949	330949	Gomez, Jason	2A Doc Num: _____

**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		COGCCinspections@Anadarko.com	All Inspections
Kulmann, Dave		dave.kulmann@state.co.us	
Avant, Paul	(720) 929-6457	Paul.Avant@Anadarko.com	All Inspections

**Compliance Summary:**QtrQtr: NENE Sec: 25 Twp: 3N Range: 68W**Inspector Comment:****Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
256762	WELL	PR	02/06/2007	GW	123-19922	HSR-WAGNER 1-25AX	PR	<input checked="" type="checkbox"/>
436593	WELL	DG	06/18/2014		123-39189	BAREFOOT 30C-25HZ	WK	<input checked="" type="checkbox"/>
436596	WELL	DG	06/16/2014		123-39191	BAREFOOT 31C-25HZ	WK	<input checked="" type="checkbox"/>
436704	WELL	DG	06/17/2014		123-39231	BAREFOOT 30N-25HZ	WK	<input checked="" type="checkbox"/>

**Equipment:**Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: <u>4</u>	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: <u>3</u>
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location**

Emergency Contact Number (S/A/V): \_\_\_\_\_

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

<b>Spills:</b>					
Type	Area	Volume	Corrective action	CA Date	
<input type="checkbox"/> Multiple Spills and Releases?					
<b>Equipment:</b>					
Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Ancillary equipment	2	SATISFACTORY	Light stations w/ lights directed toward center of operation and down to the ground not operational at time of inspection		
<b>Venting:</b>					
Yes/No		Comment			
NO					
<b>Flaring:</b>					
Type	Satisfactory/Action Required		Comment	Corrective Action	CA Date
<b>Predrill</b>					
Location ID: 330949					
<b>Site Preparation:</b>					
Lease Road Adeq.:		Pads:		Soil Stockpile:	
<b>S/AV:</b>					
Corrective Action:			Date:		CDP Num.:
<b>Form 2A COAs:</b>					
<b>S/AV:</b>		<b>Comment:</b>			
<b>CA:</b>					<b>Date:</b>
<b>Wildlife BMPs:</b>					
BMP Type	Comment				
Planning	604c.(2).R. Tank Specifications: Two 500 barrel skid-mounted frac tanks will be temporarily placed on-site for use of the pre-spud rig only. One tank will store water and the other will store water based mud.				
General Housekeeping	604c.(2).P. Removal of Surface Trash: A commercial size trash bin for removing debris will be located on site. This bin will be for use by all parties affiliated with the operation.				
Noise mitigation	604c.(2).A. Noise: Pending a safety review after construction of the location, sound mitigation barriers (hay bales) will be placed along the southeastern sides of the pad location to damper noise during drilling and completions to the nearby building unit. Sound surveys that have been conducted on each rig type are utilized to anticipate any additional noise mitigation once a drilling rig is determined.				
Final Reclamation	604c.(2).U. Identification of Plugged and Abandoned Wells: Pursuant to rule 319.a.(5)., once the well has been plugged and abandoned, KMG will identify the location of the wellbore with a permanent monument that will detail the well name and date of plugging.				
Traffic control	604c.(2).D. Traffic Plan: If required by the local government, a traffic plan will be coordinated with the local jurisdiction prior to commencement of operations.				
Construction	604c.(2).G. Berm Construction: Kerr-McGee will create tertiary containment by construction of a berm or diversion dike, site grading, or other comparable measures sufficient to further protect the ditch located 535' east of the proposed oil and gas location.				

Inspector Name: Gomez, Jason

Drilling/Completion Operations	604c.(2).I. BOPE Testing for Drilling Operations: Upon initial rig-up, BOPEs will be tested at a minimum of every 30 days.
Drilling/Completion Operations	604c.(2).H. BOPE: Our rigs at a minimum will have a double ram with blind and pipe ram; and annular preventer.
Planning	604c.(2).Q. Guy Line Anchors: Should guy line anchors be left buried for future use, they shall be identified by a bright marker greater than four (4) feet high and no more than one (1) foot east of the guy line anchor.
General Housekeeping	604c.(2).O. Loadlines: All loadlines shall be bullplugged or capped.
Construction	604c.(2).M. Fencing Requirements: The completed wellsites will be surrounded with a fence and gate with adequate lock to restrict access to authorized personnel only. KMG personnel will monitor the wellsites regularly upon completion of the wells. Authorized representatives and/or KMG personnel shall be on-site during drilling and completion operations.
Storm Water/Erosion Control	604c.(2).W. Site-Specific Measures: KMG maintains a Stormwater Management Plan that assesses erosion control for every KMG operated location. This location will be added to this plan once construction begins. This site will be inspected every fourteen (14) days during construction activities, every thirty (30) days after construction is completed, and after any major weather event.
Drilling/Completion Operations	604c.(2).J. BOPE for Well Servicing Operations: Blowout prevention equipment will be used on any servicing operations associated with this well. Backup stabbing valves will be used during any future servicing operations during reverse circulation. Valves shall be pressure tested before each well servicing operation using low-pressure air and high-pressure fluid.
Planning	604c.(2).S. Access Roads: KMG will utilize a lease access road from Highway 66 for drilling operations and maintenance equipment. The road will be properly constructed and maintained to accommodate for local emergency vehicle access. Water will be placed on dirt access roads to mitigate dust as needed. If feasible, magnesium chloride will also be used as needed on access roads to further abate dust.
Drilling/Completion Operations	604c.(2).B. Closed Loop Drilling System: KMG will use a closed loop or "pitless" system for drilling and fluid management and will not construct a reserve pit.
Planning	604c.(2).V. Development From Existing Well Pads: KMG will locate the three proposed horizontal wells on the existing well pad with location ID #330949 to reduce the amount of surface disturbance associated with this project.
Material Handling and Spill Prevention	604c.(2).N. Control of Fire Hazards: KMG and its contractors will employ best management practices during the drilling and production of its wells and facilities and will comply with appropriate COGCC rules concerning safety and fire. KMG will ensure that any material that might be deemed a fire hazard will remain no less than twenty-five (25) feet from the wellhead(s), tanks and separator(s).
Drilling/Completion Operations	604c.(2).L. Drill Stem Tests: No drill stem tests are planned and none will be performed without prior approval from the Director.
Planning	604c.(2).E. Multiwell Pads: In order to reduce surface impact, this application is for a three-well pad to be added to an existing one-well pad.
Drilling/Completion Operations	604c.(2).K. Pit Level Indicators: All tanks (used in lieu of pits) contain pit level monitors with Electronic Drilling Recorders (EDR). KMG uses EDRs with pit level monitor(s) and alarm(s) for production rigs. Basic level gauges are used on tanks utilized for the surface rig.
Final Reclamation	604c.(2).T. Well Site Cleared: The wellsite will be cleared of all non-essential equipment within ninety (90) days after all wells associated with the pad have been plugged and abandoned.

**S/A/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Stormwater:**

**Comment:** \_\_\_\_\_

**Staking:**

**On Site Inspection (305):**

**Surface Owner Contact Information:**

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Inspector Name: Gomez, Jason

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

**Facility**

Facility ID: 256762 Type: WELL API Number: 123-19922 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR temp SI for flow back

Facility ID: 436593 Type: WELL API Number: 123-39189 Status: DG Insp. Status: WK

**Complaint**

Comment: On 1-14-2015, I was contacted by the COGCC office in reference to two loud noise complaints and vehicles tracking mud from the Barefoot locations located near the intersection of Hwy 66 and Weld County Rd 13. The complaints were documented in Form 18 doc #s 200421420 and #200421435. I contacted the two complainants and both indicated the noise they had experienced was increasingly louder on Saturday 1-10-2015. Mrs. Schreiber also complained about traffic coming off of these e locations and tracking mud onto WCR 13. After speaking to the complainants, I proceeded to perform site inspections at the following locations:  
Barefoot 30C-25HZ No activity at this location. Flow back equipment was on location but there were no active operations on location. See inspection Doc# 673801675 for further information.  
Barefoot 32N-25HZ Active frac operation at location. Upon inspection, I observed mud transferred from the location to WCR 13. I observed a vehicle tracking pad on the lease road to location but the pad had been filled in by mud and debris which allowed the mud from location to be transferred to WCR 13. Upon entering the site I observed noise mitigation to the east of the location with hay bales set up as sound mitigation. The area toward the northeast, which is toward the complainants' houses, did not have any sound mitigation set up. I performed a sound study approx 350' to the northeast of the frac operation. Results of the sound study indicated the frac operation was operating within the operational limits of the COGCC sound rules. See Inspection Doc# 673801670 for further information, results of sound study, attached photos and corrective actions of vehicle tracking issues.  
Barefoot 32C-25HZ I observed vehicles had transferred mud from this location onto WCR 13. I observed a vehicle tracking pad on the lease road to location but the pad had been filled in by mud and debris which allowed the mud from location to be transferred to WCR 13. The location had bales of hay set up to the east and the north of the location. I observed flow back operations being set up at the location and frac equipment was being removed from the location. I performed a sound study approximately 350' to the northeast of the location. Results of the sound study indicated the flow back operation was operating within the operational limits of the COGCC sound rules. See Doc# 673801665 for the results of the sound study and corrective actions of vehicle tracking issues.  
I discussed these issues with the operator and the operator agreed to install more rock in the vehicle tracking pad and the operator would have a street sweeper at location to clean any excess mud tracked onto WCR 13.

**Workover**

Comment: No personel on location 8 frac tanks on location 1 open top tank with plastic wall containment GPS 40.20322 - 104.94356 also 1 tank w/ containment located GPS 40.20323 -104.94309 for flow back no activity of operation on the location. Sound mitigation bales installed to the east of the location dirt wall installed to the North of location.

Facility ID: 436596 Type: WELL API Number: 123-39191 Status: DG Insp. Status: WK

**Complaint**

Comment: No personel on location

Inspector Name: Gomez, Jason

Facility ID: 436704 Type: WELL API Number: 123-39231 Status: DG Insp. Status: WK

**Complaint**

Comment: No personel on location

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_  
 Comment: \_\_\_\_\_  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_  
 Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_  
 Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

Lat \_\_\_\_\_ Long \_\_\_\_\_  
 DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

**Complaint:**

Tracking Num	Category	Assigned To	Description	Incident Date
200421420	NOISE	Precup, Jim	<p><b>**This is the second complaint see Doc # 200420839 **</b></p> <p>Location: Barefoot facility, Co 66 and Weld Counny Road 13, southwest corner</p> <p>Continuation of an existing noise complaint investigated on 01/05/2015. The noise this morning is worse than ever before - I probably have excess of 70 db inside a closed house with closed windows, nearly 1/2 mile from the site. The original noise complaint was investigated by COGCC, recommendation were made to the operator, but as of today none of the changes have been made. The operator seems to generate the most noise when they know that the investigator will not be available to check on the noise (e.g. during the week, it's been the worst from about 8pm to 3 or 4 am the next morning.</p>	01/11/2015
200421435	ACCESS	Precup, Jim	<p>The road conditions from the well traffic makes the roads a muddy/dusty mess. Which impacts the safety of these roads and impacts the air quality. I can say that in the past few months our concrete drive has started to heave. I have lived here for 17 years and for this to start now I would say has a direct tie into the vibration of the earth caused by the well activity. If one was to try to sell their home now, who would consider buying in this area that has become noise laden, semi truck playground, which was a beautiful, quiet, and peaceful environment. This environment exists.</p>	01/12/2015
200421435	NOISE	Precup, Jim	<p><b>**Location: Intersection SHW66 &amp; CO Blvd (CR13) including one to two miles south on CR13.**</b></p> <p>Loud noise night and day from the well(s). I have a medical issue that is aggravated by ongoing loud noise, which is extremely detrimental to my health and quality of life.</p>	01/12/2015

Emission Control Burner (ECB): \_\_\_\_\_

Inspector Name: Gomez, Jason

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: IRRIGATED

Comment: \_\_\_\_\_

1003a. Debris removed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Waste Material Onsite? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors removed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation \_\_\_\_\_

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: IRRIGATED

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Inspector Name: Gomez, Jason

Debris removed _____	No disturbance /Location never built _____
Access Roads _____	Regraded _____
Gravel removed _____	Contoured _____
Location and associated production facilities reclaimed _____	Culverts removed _____
Compaction alleviation _____	Locations, facilities, roads, recontoured _____
Dust and erosion control _____	
Non cropland: Revegetated 80% _____	Cropland: perennial forage _____
Weeds present _____	Subsidence _____
Comment: _____	
Corrective Action: _____	Date _____
Overall Final Reclamation _____	Well Release on Active Location <input type="checkbox"/> Multi-Well Location <input type="checkbox"/>

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Gravel	Pass	VT	Pass	

S/A/V: SATISFACTOR Y Corrective Date: \_\_\_\_\_

Comment: Vehicle tracking cattle guard installed as well as veh tracking pad on lease road to location no sign of vehicle tracking from this location to WCR 13 at time of inspection see attached photo

CA: \_\_\_\_\_

Pits: ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673801676	Veh tracking pad and WCR 13	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3533579">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3533579</a>