

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES
----	----	----	----

Inspection Date:

01/16/2015

Document Number:

673801680

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	431161	431161	Gomez, Jason	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
, Inspections		COGCCinspections@Anadarko.com	All Inspections
Avant, Paul	(720) 929-6457	Paul.Avant@Anadarko.com	All Inspections
Kulmann, Dave		dave.kulmann@state.co.us	

Compliance Summary:QtrQtr: NWNW Sec: 15 Twp: 1N Range: 68W**Inspector Comment:****Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
431166	WELL	DG	10/26/2014	LO	123-36449	BADGER 22N-3HZ	DG	<input checked="" type="checkbox"/>
431167	WELL	DG	11/01/2014	LO	123-36450	BADGER 12N-3HZ	DG	<input checked="" type="checkbox"/>
431168	WELL	DG	10/23/2014	LO	123-36451	BUFFALO 14C-15HZ	DG	<input checked="" type="checkbox"/>
431169	WELL	DG	11/05/2014	LO	123-36452	BUFFALO STATE 34N-15HZ	DG	<input checked="" type="checkbox"/>
431170	WELL	DG	10/27/2014	LO	123-36453	BADGER 12C-3HZ	DG	<input checked="" type="checkbox"/>
431171	WELL	DG	10/29/2014	LO	123-36454	BUFFALO 35C-15HZ	DG	<input checked="" type="checkbox"/>
431172	WELL	DG	10/20/2014	LO	123-36455	BUFFALO 14N-15HZ	DG	<input checked="" type="checkbox"/>
431173	WELL	DG	10/22/2014	LO	123-36456	BADGER 22C-3HZ	DG	<input checked="" type="checkbox"/>
431174	WELL	DG	10/16/2014	LO	123-36457	BADGER 25N-3HZ	DG	<input checked="" type="checkbox"/>
431175	WELL	DG	10/21/2014	LO	123-36458	BADGER 11N-3HZ	DG	<input checked="" type="checkbox"/>

Inspector Name: Gomez, Jason

431176	WELL	DG	11/02/2014	LO	123-36459	BUFFALO 13C-15HZ	DG	X
431177	WELL	DG	10/19/2014	LO	123-36460	BUFFALO 36C-15HZ	DG	X
431178	WELL	DG	10/30/2014	LO	123-36461	BUFFALO 13N-15HZ	DG	X
431179	WELL	DG	10/24/2014	LO	123-36462	BUFFALO 35N-15HZ	DG	X
431180	WELL	DG	11/02/2014	LO	123-36463	BADGER STATE 32C-3HZ	DG	X
431181	WELL	DG	10/17/2014	LO	123-36464	BADGER 11C-3HZ	DG	X

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: <u>2</u>	Wells: <u>16</u>	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: <u>16</u>
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Venting:

Yes/No	Comment
NO	

Flaring:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 431161

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:**Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Facility**

Facility ID: 431166 Type: WELL API Number: 123-36449 Status: DG Insp. Status: DG

Complaint

Comment: On 1-16-2015 I was contacted by COGCC complaint Dept. in reference to a noise complaint at 3626 WCR 7 in Erie Colorado, complaint doc#200421743. I contacted the complainant Al Towndrow by phone he indicated he was experiencing noise coming from a drilling rig located to the northeast of his home. The complainant said he had also observed his outside faucet vibrating from the noise coming from the rig. The complainant gave me permission to go to his residence to perform a sound study. I performed a sound study approx 25' from the NE corner of the complainant residence. See inspection doc # 673801680 for further information of site inspection attached photos, and sound study. Results of the sound study indicated the drilling operation was operating within the operational limits of the COGCC sound rules. I observed sound mitigation set around the south and the west side of the location. After speaking with the operator they indicated they would be completing the hole they were on within the next day and after that they were putting the rig on electric operation in an attempt to lower the noise at the location.

Facility ID: 431167 Type: WELL API Number: 123-36450 Status: DG Insp. Status: DG

Inspector Name: Gomez, Jason

Facility ID:	431168	Type:	WELL	API Number:	123-36451	Status:	DG	Insp. Status:	DG
Facility ID:	431169	Type:	WELL	API Number:	123-36452	Status:	DG	Insp. Status:	DG
Facility ID:	431170	Type:	WELL	API Number:	123-36453	Status:	DG	Insp. Status:	DG
Facility ID:	431171	Type:	WELL	API Number:	123-36454	Status:	DG	Insp. Status:	DG
Facility ID:	431172	Type:	WELL	API Number:	123-36455	Status:	DG	Insp. Status:	DG
Facility ID:	431173	Type:	WELL	API Number:	123-36456	Status:	DG	Insp. Status:	DG
Facility ID:	431174	Type:	WELL	API Number:	123-36457	Status:	DG	Insp. Status:	DG
Facility ID:	431175	Type:	WELL	API Number:	123-36458	Status:	DG	Insp. Status:	DG
Facility ID:	431176	Type:	WELL	API Number:	123-36459	Status:	DG	Insp. Status:	DG
Facility ID:	431177	Type:	WELL	API Number:	123-36460	Status:	DG	Insp. Status:	DG
Facility ID:	431178	Type:	WELL	API Number:	123-36461	Status:	DG	Insp. Status:	DG
Facility ID:	431179	Type:	WELL	API Number:	123-36462	Status:	DG	Insp. Status:	DG
Facility ID:	431180	Type:	WELL	API Number:	123-36463	Status:	DG	Insp. Status:	DG
Facility ID:	431181	Type:	WELL	API Number:	123-36464	Status:	DG	Insp. Status:	DG

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Complaint:				
Tracking Num	Category	Assigned To	Description	Incident Date
200421743	NOISE	Gomez, Jason	MOSTLY NIGHT TIME NOISE FROM RIG, CAN BE HEARD IN HOUSE, ALSO GROUND VIBRATION ON AND OFF AT TIMES.	01/16/2015

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: DRY LAND, IRRIGATED

Comment: _____

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION**Cropland**

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Inspector Name: Gomez, Jason

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: DRY LAND, IRRIGATED

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				MHSP	Pass	
Berms	Pass			CM	Pass	

S/A/V: SATISFACTOR
Y

Corrective Date: _____

Comment: _____

CA: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673801680	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3533613
673801685	Sound study reults	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3533580
673801686	Sound Mitigation	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3533581