



Industrial Ecosystems Inc.
 Soil Reclamation Center

P.O. Box 2043
 Farmington NM 87499

Phone: (505) 632-1782
 Fax: (505) 632-1876

#49 CR 3150
 Aztec NM 87410

Material Entry Record

Date: 12/10/14 Company Representatives Name: Michael Sandaal

Generator of Material: Dugan Phone Number: _____

Origin of Material (Location): Tiffany #1 Rig # _____

Material Transported by: Ralph Miller H2S Gas Non-Detect Detect: Level _____

Driver's Name: Mike Paint Filter Test: Passed Failed

DENIED / REJECTED

Type of Material

Soil
 Gravel
 Other: _____

Tank Bottom Sludge
 Tank Cleaning Residue
 Drilling Fluids/Mud

	Amount of Material							
	Load #1	Load #2	Load #3	Load #4	Load #5	Load #6	Load #7	Load #8
Cubic Yards (5 cy min)	5							
Barrels (5 bbl min)								
Truck #	07A							
Wash Out (5 bbl min)	<input type="checkbox"/>							
Washed out by:								
Roll-Off #								
Scraped	<input type="checkbox"/>							
Wash Out (5 bbl min)	<input type="checkbox"/>							
Washed out by:								
Time In (am/pm)	7:09a							
Time Out (am/pm)	7:43a							
Login Initials	KS							
Driver Initials	MO							

Exempt
 Non-Exempt

- Facility Fee For Truck/Tank/Roll-off Bin Washout x _____
- Roll-Off Box Scrape Out Fee x _____
- 1/2 hr. Loader Time for "flipping pit" x _____
- Blending/Dilution Required
- Tested x 1

- Logged on Biopile Sheet
- Logged on Daily Log Form
- Logged on C-138

I certify that the quantity and type of waste is that listed above. To the best of my knowledge, no other quantities or types of wastes have been added or removed.

Driver's signature: Mike
 Attendant's Signature: R. Selph

Total cy: 5
 Total bbls: _____