

Site Photos: Facility# 292827

Date: January 20, 2015



photo 1: Center of the location facing north.



photo 2: Center of the location facing west.

Site Photos: Facility# 292827

Date: January 20, 2015



photo 3: Center of the location facing south.



photo 4: Center of the location facing east.

Site Photos: Facility# 292827

Date: January 20, 2015



photo 5: Southwest corner of the location facing northeast.



photo 6: Northeast corner of the location facing southwest.

Site Photos: Facility# 292827

Date: January 20, 2015



photo 7: Power line ending at the northeast corner of the location.



photo 8: Northeast corner of the location facing west.

Site Photos: Facility# 292827

Date: January 20, 2015



photo 9: Northwest corner of the location facing southeast.



photo 10: Pipeline risers at the northwest corner of the location.

Site Photos: Facility# 292827

Date: January 20, 2015



photo 11: Gas pipeline marker.



photo 12: Northwest corner of the location facing south.

Site Photos: Facility# 292827

Date: January 20, 2015



photo 13: Pipe and debris that remains at the north side of the location.



photo 14: North side of the location facing south. Gravel and cement debris remains.

Site Photos: Facility# 292827

Date: January 20, 2015



photo 15: Unidentified pipe marker remains at the northeast corner of the location.



photo 16: Metal trash debris remains on the east side of the location.

Site Photos: Facility# 292827

Date: January 20, 2015



photo 17: Plastic fabric debris exposed on location.



photo 18: Cement debris and gravel piles remain throughout location.

Site Photos: Facility# 292827

Date: January 20, 2015



photo 19: Wire cables exposed from the ground on the south side of the location.



photo 20: Surrounding crop vegetation around the location.