

USA 1-5 LW

Inspection# 675201123

Wellhead sign missing
nearest public access.



Unused equipment on
location.



Access road.



Access road.

