

Site Photos: API# 05-121-10876

Date: January 27, 2015



photo 1: Access road facing east, no vegetation growth 150'x15' along the access road.



photo 2: Access road facing east towards the location.

Site Photos: API# 05-121-10876

Date: January 27, 2015



photo 3: Center of the location facing north.



photo 4: Center of the location facing west.

Site Photos: API# 05-121-10876

Date: January 27, 2015



photo 5: Center of the location facing south.



photo 6: Center of the location facing east.

Site Photos: API# 05-121-10876

Date: January 27, 2015



photo 7: East side of the location does not have adequate vegetation cover.



photo 8: Surrounding vegetation cover.