

## Horseshoe Canyon 1-33

Inspection# 675201137

Label peeling.



Erosion on south side of location.





Erosion on south side of  
location.



Erosion along entrance.

