

Site Photos: API# 05-121-10999

Date: January 28, 2015



photo 1: Facing northeast towards the location along the access road.



photo 2: Access road to the northeast towards the location.

Site Photos: API# 05-121-10999

Date: January 28, 2015



photo 3: Center of the location facing north.



photo 4: Center of the location facing west.

Site Photos: API# 05-121-10999

Date: January 28, 2015



photo 5: Center of the location facing south.



photo 6: Center of the location facing east.

Site Photos: API# 05-121-10999

Date: January 28, 2015



photo 7: West side of the location facing east towards the location. Location is fenced.



photo 8: Weed growth (Russian thistle) on the location.

Site Photos: API# 05-121-10999

Date: January 28, 2015



photo 9: Facing northeast, surrounding vegetation around the location.



photo 10: Facing northwest, surrounding vegetation around the location.