

**Site Photos: API# 05-121-10873**

**Date: January 28, 2015**



**photo 1:** Center of location facing south. Area with no vegetation growth approximately 75'x30' in size.



**photo 2:** South side of the location facing north. Bare area approximately 75'x30' in size.



Site Photos: API# 05-121-10873

Date: January 28, 2015



**photo 3:** Scrap metal debris was found at the center of the location.



**photo 4:** Close up view of scrap metal debris.



Site Photos: API# 05-121-10873

Date: January 28, 2015



**photo 5:** South side of location facing south. Bare area with no vegetation approx. 15'x10'.



**photo 6:** Gate and t-post remain around the perimeter of the location.