

EnCana Oil and Gas

F23 Pad

Location # 335667

Location sign



Erosion rills running down roadside of east entrance.



Cuts slope with no BMPs



Cut from hill side at west entrance.



Low spot in berm

