

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES
----	----	----	----

Inspection Date:

02/04/2015

Document Number:

674700953

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	335786	335786	LONGWORTH, MIKE	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Inspections, General	970-285-2665	cogcc.inspections@encana.com	EnCana Inspection email

Compliance Summary:QtrQtr: SENE Sec: 22 Twp: 5S Range: 96W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
05/22/2012	663800354			SATISFACTORY			No

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
274560	WELL	PR	09/29/2005	GW	045-13358	N.PARACHUTE WF07A H22 596	PR	<input checked="" type="checkbox"/>
274561	WELL	PR	02/01/2014	GW	045-13360	N.PARACHUTE WF08A H22 596	PR	<input checked="" type="checkbox"/>
274562	WELL	PR	11/01/2005	GW	045-13359	N.PARACHUTE WF08D H22 596	PR	<input checked="" type="checkbox"/>
274662	WELL	PR	10/26/2005	GW	045-13375	N. PARACHUTE WF08B H22 596	PR	<input checked="" type="checkbox"/>
274663	WELL	PR	02/01/2014	GW	045-13376	N. PARACHUTE WF07D H22 596	PR	<input checked="" type="checkbox"/>
274697	WELL	PR	08/08/2005	GW	045-13379	N. PARACHUTE WFO7C H22 596	PR	<input checked="" type="checkbox"/>
274698	WELL	PR	09/22/2005	GW	045-13378	N. PARACHUTE WF07B H22 596	PR	<input checked="" type="checkbox"/>
274849	WELL	PR	01/27/2014	GW	045-13408	N.PARACHUTE WF08C H22 596	PR	<input checked="" type="checkbox"/>
277961	PIT	CL	01/22/2013		-	N. PARACHUTE WF07A H22	CL	<input type="checkbox"/>

Equipment:**Location Inventory**

Inspector Name: LONGWORTH, MIKE

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			
BATTERY	SATISFACTORY			
CONTAINERS	SATISFACTORY			

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Equipment:

Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Ancillary equipment	2	SATISFACTORY			
Ancillary equipment	8	SATISFACTORY			
Gas Meter Run	2	SATISFACTORY			
Horizontal Heated Separator	1	SATISFACTORY			
Plunger Lift	8	SATISFACTORY			
Bird Protectors	1	SATISFACTORY			

Venting:

Yes/No	Comment
NO	

Flaring:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 335786

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 274560 Type: WELL API Number: 045-13358 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Facility ID: 274561 Type: WELL API Number: 045-13360 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Facility ID: 274562 Type: WELL API Number: 045-13359 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Inspector Name: LONGWORTH, MIKE

Facility ID: 274662 Type: WELL API Number: 045-13375 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Facility ID: 274663 Type: WELL API Number: 045-13376 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Facility ID: 274697 Type: WELL API Number: 045-13379 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Facility ID: 274698 Type: WELL API Number: 045-13378 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Facility ID: 274849 Type: WELL API Number: 045-13408 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Environmental

Spills/Releases:

Type of Spill: Description: Estimated Spill Volume:
Comment:
Corrective Action: Date:
Reportable: GPS: Lat Long
Proximity to Surface Water: Depth to Ground Water:

Water Well:

DWR Receipt Num: Owner Name: GPS : Lat Long

Field Parameters:

Sample Location:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: Date Interim Reclamation Completed:

Land Use:

Comment:

1003a. Debris removed? Pass CM _____
 CA _____ CA Date _____
 Waste Material Onsite? Pass CM _____
 CA _____ CA Date _____
 Unused or unneeded equipment onsite? Pass CM _____
 CA _____ CA Date _____
 Pit, cellars, rat holes and other bores closed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors removed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors marked? _____ CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Inspector Name: LONGWORTH, MIKE

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction	Pass			
Berms	Pass					
		Ditches	Pass			
				VT	Pass	Speed limit 25 mph
Compaction	Pass					
				MHSP	Pass	secondary containment under containers
Seeding						
Gravel	Pass					
		Gravel	Pass			
		Culverts	Pass			
		Check Dams	Pass			
Ditches	Pass					

S/A/V: SATISFACTOR Y Corrective Date: _____

Comment: Limited inspection due to snow cover bmps

CA: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	277961	1417862	