

WPX Energy

Federal 102-3 Pad

Location # 334863

COC46603

Rusty tank and subsidence of berm base and wall where earth work has been done.



Erosion of BMPs



Erosion of BMPs



Erosion of surface around check dam



Erosion of hillside behind tank battery and equipment

