

WPX Energy

GR 1-3 SH

Location # 334812

COC 24603

Wells and tank battery.



Erosion of check dam and along drainage hose.



Trap full of sediment and erosion of outlet off hillside.



Drain hose in erosion rill. Sediment built up at straw bales.

