

Government 6

Inspection# 675201166

Pump jack at wellhead.
Production equipment has
been removed



Sign missing nearest public
access.



Gas meter on location.

