

Site Photos: API# 05-011-06036

Date: February 5, 2015



photo 1: Facing north along access road from the location.



photo 2: Pipeline riser remains on the location. Lat/Long: 38.06377/-102.80730

Site Photos: API# 05-011-06036

Date: February 5, 2015



photo 3: Center of the location facing north.



photo 4: Center of the location facing west.

Site Photos: API# 05-011-06036

Date: February 5, 2015



photo 5: Center of the location facing south.



photo 6: Center of the location facing east.

Site Photos: API# 05-011-06036

Date: February 5, 2015



photo 7: West side of the location facing east towards disturbance area.



photo 8: East side of the location facing west towards disturbance area.

Site Photos: API# 05-011-06036

Date: February 5, 2015



photo 9: Weed growth (Russian thistle) throughout the location.



photo 10: Facing southeast, surrounding/reference area vegetation.