

GV 86-2 Pad

Inspection# 675201155

Erosion at outlet of culvert.

39.46521/-107.96420



Road side erosion.

39.46707/-107.96320



Road side erosion.

39.46707/-107.96320



Road side erosion.

39.46843/-107.96270



Road side erosion.

39.46843/-107.96270

