

GV 65-2 Pad

Inspection# 675201157

Erosion on access road.

39.47243/-107.96942



Erosion on access road.

39.47243/-107.96942



Unstabilized area of
location.

