

**PA 32-3 Pad**

Inspection# 675201159

Tank with incomplete  
signage.



Location is not stabilized.

