

W 22-3 Pad

Inspection# 675201160

Access road is not stabilized.



Access road is not stabilized.



Road side erosion at entrance.



Road side erosion at entrance and sediment migration.



Location is not stabilized.

