

PA 21-3 Pad

Inspection# 675201161

Access road and location are not stabilized.



Unstabilized area of location.



Road side erosion at entrance.



Road side erosion at entrance and sediment migration.



Location is not stabilized.

