

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES
----	----	----	----

Inspection Date:
02/04/2015Document Number:
675201164Overall Inspection:
SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	334569	334569	CONKLIN, CURTIS	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 96850Name of Operator: WPX ENERGY ROCKY MOUNTAIN LLCAddress: 1001 17TH STREET - SUITE #1200City: DENVER State: CO Zip: 80202

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
WPX, Energy		COGCCInspectionReports@wpxenergy.com	All Inspections

Compliance Summary:QtrQtr: NENE Sec: 4 Twp: 7S Range: 95W**Inspector Comment:****Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
257876	WELL	PR	01/05/2007	GW	045-07609	KNIGHT PA 41-4	PR	<input checked="" type="checkbox"/>
285148	WELL	PR	06/14/2006	GW	045-12381	KNIGHT PA 332-4	PR	<input checked="" type="checkbox"/>
285754	WELL	PR	07/19/2006	GW	045-12554	KNIGHT PA 42-4	PR	<input checked="" type="checkbox"/>
285755	WELL	PR	07/19/2006	GW	045-12548	KNIGHT PA 531-4	PR	<input checked="" type="checkbox"/>
285756	WELL	PR	07/19/2006	GW	045-12549	KNIGHT PA 341-4	PR	<input checked="" type="checkbox"/>
285758	WELL	PR	07/19/2006	GW	045-12547	KNIGHT PA 441-4	PR	<input checked="" type="checkbox"/>
285760	WELL	PR	07/19/2006	GW	045-12546	KNIGHT PA 431-4	PR	<input checked="" type="checkbox"/>
285762	WELL	PR	07/19/2006	GW	045-12545	KNIGHT PA 32-4	PR	<input checked="" type="checkbox"/>
285764	WELL	PR	07/19/2006	GW	045-12550	KNIGHT PA 432-4	PR	<input checked="" type="checkbox"/>
285766	WELL	PR	04/11/2007	GW	045-12551	KNIGHT PA 532-4	PR	<input checked="" type="checkbox"/>
285768	WELL	PR	07/19/2006	GW	045-12552	KNIGHT PA 342-4	PR	<input checked="" type="checkbox"/>
285771	WELL	PR	04/11/2007	GW	045-12553	KNIGHT PA 442-4	PR	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location**Lease Road:**

Type	Satisfactory/Action Required	comment	Corrective Action	Date
Access	SATISFACTORY			

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
CONTAINERS	SATISFACTORY			
WELLHEAD	SATISFACTORY			
TANK LABELS/PLACARDS	SATISFACTORY			

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: _____

Comment: **970-285-9377**

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?**Fencing/:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
SEPARATOR	SATISFACTORY	Wire panels		
TANK BATTERY	SATISFACTORY	Wire panels		
WELLHEAD	SATISFACTORY	Wire panels		
LOCATION	SATISFACTORY	Wire fence		

Equipment:

Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Plunger Lift	12	SATISFACTORY			
Ancillary equipment	3	SATISFACTORY	Chem units w/ containment		
Deadman # & Marked	2	SATISFACTORY			
Horizontal Heated Separator	12	SATISFACTORY			
Bird Protectors	6	SATISFACTORY			

Facilities:☐ New Tank

Tank ID: _____

Inspector Name: CONKLIN, CURTIS

Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	2	200 BBLS	STEEL AST	,
S/A/V:	SATISFACTORY		Comment:	
Corrective Action:				Corrective Date:

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Corrective Action				Corrective Date
Comment	Same			

Facilities: ☐ New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
CONDENSATE	2	300 BBLS	STEEL AST	,
S/A/V:	SATISFACTORY		Comment:	
Corrective Action:				Corrective Date:

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Corrective Action				Corrective Date
Comment				

Venting:

Yes/No	Comment

Flaring:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 334569

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 257876 Type: WELL API Number: 045-07609 Status: PR Insp. Status: PR

Producing Well

Comment: PR w/ plunger

Facility ID: 285148 Type: WELL API Number: 045-12381 Status: PR Insp. Status: PR

Producing Well

Comment: PR w/ plunger

Facility ID: 285754 Type: WELL API Number: 045-12554 Status: PR Insp. Status: PR

Producing Well

Comment: PR w/ plunger

Facility ID: 285755 Type: WELL API Number: 045-12548 Status: PR Insp. Status: PR

Producing Well

Comment: PR w/ plunger

Facility ID: 285756 Type: WELL API Number: 045-12549 Status: PR Insp. Status: PR

Producing Well

Comment: PR w/ plunger

Facility ID: 285758 Type: WELL API Number: 045-12547 Status: PR Insp. Status: PR

Producing Well

Comment: PR w/ plunger

Facility ID: 285760 Type: WELL API Number: 045-12546 Status: PR Insp. Status: PR

Producing Well

Comment: PR w/ plunger

Facility ID: 285762 Type: WELL API Number: 045-12545 Status: PR Insp. Status: PR

Producing Well

Comment: PR w/ plunger

Facility ID: 285764 Type: WELL API Number: 045-12550 Status: PR Insp. Status: PR

Producing Well

Comment: PR w/ plunger

Facility ID: 285766 Type: WELL API Number: 045-12551 Status: PR Insp. Status: PR

Producing Well

Comment: PR w/ plunger

Facility ID: 285768 Type: WELL API Number: 045-12552 Status: PR Insp. Status: PR

Producing Well

Comment: PR w/ plunger

Facility ID: 285771 Type: WELL API Number: 045-12553 Status: PR Insp. Status: PR

Producing Well

Comment: PR w/ plunger

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____

Inspector Name: CONKLIN, CURTIS

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____
CA _____ CA Date _____
Waste Material Onsite? _____ CM _____
CA _____ CA Date _____
Unused or unneeded equipment onsite? _____ CM _____
CA _____ CA Date _____
Pit, cellars, rat holes and other bores closed? _____ CM _____
CA _____ CA Date _____
Guy line anchors removed? _____ CM _____
CA _____ CA Date _____
Guy line anchors marked? _____ CM _____
CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Inspector Name: CONKLIN, CURTIS

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads _____

Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: _____

Corrective Date: _____

Comment: _____

CA: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675201164	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3547743