

Site Photos: API# 05-043-40025

Date: February 10, 2015



photo 1: Center of the location facing north.



photo 2: Center of the location facing west.

Site Photos: API# 05-043-40025

Date: February 10, 2015



photo 3: Center of the location facing south.



photo 4: Center of the location facing east.

Site Photos: API# 05-043-40025

Date: February 10, 2015



photo 5: Weed growth (Russian thistle) throughout the location.



photo 6: Scrap metal found on the east side of the location.

Site Photos: API# 05-043-40025

Date: February 10, 2015



photo 7: Debris found on location (wood, nails).



photo 8: Facing north, surrounding/reference area vegetation around the location.