

Site Photos: API# 05-043-06059

Date: February 10, 2015



photo 1: Facing west along access road to the location. The road has not been reclaimed.



photo 2: Erosion is occurring along the access road and a deep gully (~2ft.) has formed.

Site Photos: API# 05-043-06059

Date: February 10, 2015



photo 3: Center of the location facing north.



photo 4: Center of the location facing west.

Site Photos: API# 05-043-06059

Date: February 10, 2015



photo 5: Center of the location facing south.



photo 6: Center of the location facing east.

Site Photos: API# 05-043-06059

Date: February 10, 2015



photo 7: Weed growth (Russian thistle) throughout the location.



photo 8: Facing southeast, surrounding vegetation around the location.