

WPX Energy

GM 220-33 Pad

Location # 335319

Erosion rills running off location behind tank



Erosion of check dam



Back fill in ditch.

