

EnCana Oil and Gas

K-25A

Location # 335649

Unstable cut wall behind wells



Unstable cut wall



Obstruction of ditch flow

