



Photo 1. View of new cobble armoring and straw wattles in northeastern corner of project area.



Photo 2. View of new berm along northern edge of working area.



Photo 3. View of new cobble and straw wattle stormwater BMP where concentrated stormwater flows exit the northern portion of the project area.



Photo 4. View of newly installed straw wattle placed along the western edge of the project area.



Photo 5. View of newly installed straw wattle on western edge. This will need monitoring to prevent additional sediment loss and erosion in area where erosional channels have formed.