

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

| | | | |
|----|----|----|----|
| DE | ET | OE | ES |
|----|----|----|----|

Inspection Date:
02/19/2015Document Number:
666800677Overall Inspection:
SATISFACTORY**FIELD INSPECTION FORM**

| | | | | | |
|---------------------|-------------|--------|-----------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | 2A Doc Num: |
| | 259676 | 334796 | Murray, Richard | <input type="checkbox"/> | |

Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|-------|------------------------------|---------|
| Contact, General | | cogcc.inspections@encana.com | |

Compliance Summary:QtrQtr: SWNW Sec: 8 Twp: 7S Range: 92W

| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|-------------------------------|----------|----------------|-----------------|
| 01/28/2011 | 200294364 | PR | PR | SATISFACTORY | | | No |
| 06/12/2001 | 200020465 | PR | WO | SATISFACTORY | | Pass | No |
| 04/11/2001 | 200017295 | DG | ND | SATISFACTORY | | Pass | No |

Inspector Comment:**Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status | |
|-------------|------|--------|-------------|------------|-----------|----------------------|-------------|-------------------------------------|
| 114894 | PIT | | 09/23/1999 | | - | CHRISTNER 8-5 | | <input type="checkbox"/> |
| 211579 | WELL | PR | 05/15/2002 | GW | 045-07340 | CHRISTNER 8-5 (E8E) | PR | <input checked="" type="checkbox"/> |
| 259675 | WELL | PR | 04/02/2001 | GW | 045-07762 | CHRISTNER 8-5B (E8E) | PR | <input checked="" type="checkbox"/> |
| 259676 | WELL | PR | 04/02/2001 | GW | 045-07761 | CHRISTNER 8-5A (E8E) | PR | <input checked="" type="checkbox"/> |

Equipment:**Location Inventory**

| | | | |
|-----------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Motors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location**Signs/Marker:**

| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|---------|------------------------------|---------|-------------------|---------|
| BATTERY | SATISFACTORY | | | |

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

| Type | Area | Volume | Corrective action | CA Date |
|------|------|--------|-------------------|---------|
|------|------|--------|-------------------|---------|

☐ Multiple Spills and Releases?**Equipment:**

| Type | # | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|-----------------------------|---|------------------------------|---------|-------------------|---------|
| Horizontal Heated Separator | 3 | SATISFACTORY | | | |
| Plunger Lift | 3 | SATISFACTORY | | | |

Venting:

| Yes/No | Comment |
|--------|---------|
| NO | |

Flaring:

| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|------|------------------------------|---------|-------------------|---------|
| | | | | |

Predrill

Location ID: 259676

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 211579 Type: WELL API Number: 045-07340 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Facility ID: 259675 Type: WELL API Number: 045-07762 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Facility ID: 259676 Type: WELL API Number: 045-07761 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
 Comment: _____
 Corrective Action: _____ Date: _____
 Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____
 DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): N _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): YES _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? Pass CM _____ CA _____ CA Date _____
 Waste Material Onsite? Pass CM _____ CA _____ CA Date _____
 Unused or unneeded equipment onsite? Pass CM _____ CA _____ CA Date _____
 Pit, cellars, rat holes and other bores closed? Pass CM _____ CA _____ CA Date _____
 Guy line anchors removed? Pass CM _____ CA _____ CA Date _____
 Guy line anchors marked? _____ CM _____ CA _____ CA Date _____

1003b. Area no longer in use? Pass _____ Production areas stabilized ? Pass _____

1003c. Compacted areas have been cross ripped? Pass _____

1003d. Drilling pit closed? Pass _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Inspector Name: Murray, Richard

Production areas have been stabilized? _____

Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | Gravel | Pass | | | |
| Gravel | Pass | | | | | |
| | | Culverts | Pass | | | |
| Compaction | Pass | | | | | |

S/A/V: SATISFACTOR _____

Corrective Date: _____

Y

Comment: _____

CA: _____

Pits: ☒ NO SURFACE INDICATION OF PIT