

DRILLING COMPLETION REPORT

This form is to be submitted within 30 days of the setting of production casing, the plugging of a dry hole, the deepening or sidetracking of a well, or any time the wellbore configuration is changed. If the well is deepened or sidetracked a new Form 5 is required. If an attempt has been made to complete/produce a well, then the operator shall submit Form 5A (Completed Interval Report.) If the well has been plugged, a form 6 (Well Abandonment Report) is required.

Document Number:
400539035

Date Received:
01/14/2014

Completion Type Final completion Preliminary completion

OGCC Operator Number: 100322 Contact Name: Kathleen Mills

Name of Operator: NOBLE ENERGY INC Phone: (720) 587-2226

Address: 1625 BROADWAY STE 2200 Fax: (303) 228-4286

City: DENVER State: CO Zip: 80202

API Number 05-123-37472-00 County: WELD

Well Name: Rohn State Well Number: LD09-69HN

Location: QtrQtr: SESE Section: 4 Township: 9N Range: 58W Meridian: 6

Footage at surface: Distance: 661 feet Direction: FSL Distance: 480 feet Direction: FEL

As Drilled Latitude: 40.774974 As Drilled Longitude: -103.861768

GPS Data:
Date of Measurement: 11/27/2013 PDOP Reading: 3.8 GPS Instrument Operator's Name: ELICEO CALDERON

** If directional footage at Top of Prod. Zone Dist.: 2 feet. Direction: FSL Dist.: 1156 feet. Direction: FEL
Sec: 4 Twp: 9N Rng: 58W

** If directional footage at Bottom Hole Dist.: 53 feet. Direction: FNL Dist.: 711 feet. Direction: FWL
Sec: 9 Twp: 9N Rng: 58W

Field Name: WILDCAT Field Number: 99999

Federal, Indian or State Lease Number: _____

Spud Date: (when the 1st bit hit the dirt) 09/22/2013 Date TD: 09/29/2013 Date Casing Set or D&A: 09/30/2013

Rig Release Date: _____ Per Rule 308A.b.

Well Classification:
 Dry Oil Gas/Coalbed Disposal Stratigraphic Enhanced Recovery Storage Observation

Total Depth MD 9710 TVD** 5773 Plug Back Total Depth MD 9677 TVD** 5773

Elevations GR 4712 KB 4736 **Digital Copies of ALL Logs must be Attached per Rule 308A**

List Electric Logs Run:
CBL, MUD, GR

CASING, LINER AND CEMENT

| Casing Type | Size of Hole | Size of Casing | Wt/Ft | Csg/Liner Top | Setting Depth | Sacks Cmt | Cmt Top | Cmt Bot | Status |
|-------------|--------------|----------------|-------|---------------|---------------|-----------|---------|---------|--------|
| CONDUCTOR | 18 | 16 | 84 | 0 | 124 | 80 | 0 | 124 | VISU |
| SURF | 13+3/4 | 9+5/8 | 36 | 0 | 1,240 | 492 | 0 | 1,240 | VISU |
| 1ST | 8+3/4 | 7 | 26 | 0 | 6,170 | 505 | 2,314 | 6,170 | CALC |
| 1ST LINER | 6+1/8 | 4+1/2 | 11.6 | 6007 | 9,700 | 0 | | | |

STAGE/TOP OUT/REMEDIAL CEMENT

Cement work date: _____

| Method used | String | Cementing tool setting/perf depth | Cement volume | Cement top | Cement bottom |
|-------------|--------|-----------------------------------|---------------|------------|---------------|
| | | | | | |

Details of work:

FORMATION LOG INTERVALS AND TEST ZONES

| FORMATION NAME | Measured Depth | | Check if applies | | COMMENTS (All DST and Core Analysis must be submitted to COGCC) |
|----------------|----------------|--------|------------------|-------|---|
| | Top | Bottom | DST | Cored | |
| PIERRE | 2,384 | | | | |
| PARKMAN | 3,287 | | | | |
| SUSSEX | 3,936 | | | | |
| SHANNON | 4,388 | | | | |
| TEEPEE BUTTES | 4,957 | | | | |
| NIOBRARA | 5,741 | | | | |

Comment:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Kathleen Mills

Title: Regulatory Analyst Date: 1/14/2014 Email: kmills@nobleenergyinc.com

Attachment Check List

| Att Doc Num | Document Name | attached ? | |
|-----------------------------|-----------------------|---|--|
| Attachment Checklist | | | |
| 400539164 | CMT Summary * | Yes <input checked="" type="checkbox"/> | No <input type="checkbox"/> |
| | Core Analysis | Yes <input type="checkbox"/> | No <input checked="" type="checkbox"/> |
| 400539166 | Directional Survey ** | Yes <input checked="" type="checkbox"/> | No <input type="checkbox"/> |
| | DST Analysis | Yes <input type="checkbox"/> | No <input checked="" type="checkbox"/> |
| | Logs | Yes <input checked="" type="checkbox"/> | No <input type="checkbox"/> |
| | Other | Yes <input type="checkbox"/> | No <input checked="" type="checkbox"/> |
| Other Attachments | | | |
| 400539035 | FORM 5 SUBMITTED | Yes <input checked="" type="checkbox"/> | No <input type="checkbox"/> |
| 400539047 | PDF-CEMENT BOND | Yes <input checked="" type="checkbox"/> | No <input type="checkbox"/> |
| 400539056 | LAS-MUD | Yes <input checked="" type="checkbox"/> | No <input type="checkbox"/> |
| 400539058 | PDF-MUD | Yes <input checked="" type="checkbox"/> | No <input type="checkbox"/> |
| 400539119 | LAS-MUD | Yes <input checked="" type="checkbox"/> | No <input type="checkbox"/> |
| 400539122 | PDF-MUD | Yes <input checked="" type="checkbox"/> | No <input type="checkbox"/> |
| 400539157 | PDF-GAMMA RAY | Yes <input checked="" type="checkbox"/> | No <input type="checkbox"/> |
| 400539161 | PDF-GAMMA RAY | Yes <input checked="" type="checkbox"/> | No <input type="checkbox"/> |
| 400539162 | LAS-GAMMA RAY | Yes <input checked="" type="checkbox"/> | No <input type="checkbox"/> |
| 400539167 | DIRECTIONAL DATA | Yes <input checked="" type="checkbox"/> | No <input type="checkbox"/> |
| 400791698 | PDF-MUD | Yes <input checked="" type="checkbox"/> | No <input type="checkbox"/> |
| 400796219 | DIRECTIONAL DATA | Yes <input checked="" type="checkbox"/> | No <input type="checkbox"/> |
| 400796346 | DIRECTIONAL DATA | Yes <input checked="" type="checkbox"/> | No <input type="checkbox"/> |

General Comments

| <u>User Group</u> | <u>Comment</u> | <u>Comment Date</u> |
|-------------------|---|-------------------------|
| Permit | Operator uploaded horiz. mud log .pdf. | 2/13/2015 9:30:50 AM |
| Permit | Changed field name to DJ Horiz. Niobrara. 1) Horiz. mud log .pdf corrupted. 2) Dir. survey does not match dir. data. Contacted operator. Returned to draft. | 2/11/2015 8:38:00 AM |

Total: 2 comment(s)